

2024 DEVELON DX55R-7

UNIT: DHKCEADWER6001935

Price: \$0.00 USD



GENERAL APPEARANCE

Year
2024

Make
DEVELON

Model
DX55R-7

Unit Number
C22536

Serial
DHKCEADWER6001935

Pre-Operational Checks

Confirm Fluids Checked: Engine Coolant. Confirm Fluids Checked: Engine(s) Oil. Confirm Fluids Checked: Hydraulic Fluid.
Confirm Fluids Checked: Fuel Level. N/A: Transmission Fluid

Paint

No visible damage

Body Panels

Door glass is broken and missing

Cab/Canopy Overhead Structural Framework

door glass and upper cab window are broken , door glass is missing

Steps

No visible damage or missing components

Hand Rails

Cab entry hand rail damaged, On door frame

Exterior Lights

All lights operational Light is inoperative

Serial Number / VIN

DHKCEADWER6001935

SAFETY

Travel Alarm

Operational

Horn

Operational

Seat Belts

Operational

Safety Lock Out/Stop

Operational

Swing Brake

Operational

Current Safety Manual

Yes

Current Operator/Maintenance Manual

Yes

CONTROL STATION

Seat/Armrests

No visible damage or missing components

Glass

Cab door missing, Upper cab window is cracked

Cab Door

Door frame damaged Pull handle is broken and frame is bent

Steering Controls

Rating:

Good

Hydraulic Controls

Rating:
Good

Drivetrain Controls

Rating:
Good

Dash Console

Rating:
Good

Engine Oil Pressure

The fault indicator shuts off after the engine oil pressure rises.

Warning Lights

Operational

Gauges

Operational

Rear View Camera

Camera operates as intended

Air Conditioner

Operational

Heater

Operational

Limited Function Check (Control Station)

The main components are in place and operational as noted.

Control Station

Cab Details:, Cab Type Enclosed Cab, Air Conditioner, Rear View Camera

Hour Meter / Odometer

589 hrs

Hour Meter /Odometer Usage Reading (Start)

589 hrs

ENGINE

A/C Compressor

Operational

Blow-by (Subjective Visual Observation)

No noticeable vapor or pressure

Starter

Operational

Exhaust System

No visible damage or missing components

Radiator

Rating:
Good

Oil Leaks

No dripping leaks

Fuel Leaks
No dripping leaks

Cooling System Leaks
No dripping leaks

Limited Function Check (Engine)
The engine started and ran.

Emission Status
Tier 4

Engine
2024 US EPA Label

DRIVETRAIN

Left Drive Motor
Rating:
Good

Right Drive Motor
Rating:
Good

Left Final Drive
Rating:
Good

Right Final Drive
Rating:
Good

Limited Function Check (Drivetrain)
The drivetrain was operational.

HYDRAULICS

Pumps (Hydraulics)
Rating:
Good

Valves
Rating:
Good

Hydraulic Tank
Rating:
Good

Hoses (Hydraulics)
Rating:
Good

Auxiliary Hydraulic Plumbing
Operational, Thumb hose is leaking , drip

Swing Motor

Rating:

Good

Hydraulic Center Swivel

Rating:

Good

Boom Swing Cylinders

Rating:

Good

Boom Lift Cylinder(s)

Rating:

Good

Stick Cylinder

Rating:

Good

Bucket Cylinder

Rating:

Good

Thumb Cylinder

Rating:

Good

Blade Lift Cylinder

Rating:

Good

Limited Function Check (Hydraulics)

The hydraulic system was operational.

CHASSIS

Boom/Stick Details

Standard Boom, 6 ft 2 in Stick, Backfill Blade

Boom Condition

Rating:

Good

Stick Condition

Rating:

Good

Swing Tower Pivot

Rating:

Good

Boom Base Pin And Bushings

Rating:

Good

Pin And Bushings Boom To Stick

Rating:

Good

Pin And Bushings Stick To Bucket

Rating:

Good

Pins And Bushings Stick To Coupler

Rating:

Good

Turntable Bearing

Rating:

Good

Bottom Covers

Rating:

Good

Limited Function Check (Chassis)

The main components were operational in a limited check.

RUBBER TRACK UNDERCARRIAGE

Roller Frames

Rating:

Good

Track Pads

Rating:

Good

Grouser Height Measurement

Left side: 22 mm, Right side: 22 mm

Track Belt Condition

No visible damage

Rubber Belt Drive Lugs

No visible damage

Track Tensioners

Operational

SPECIALTY

Thumb

Hydraulic thumb

Rating:

Good

Excavator Bucket Condition

Rating:

Good

Bucket Cutting Edge/Shanks/Teeth

No visible damage or missing components

Rating:

Good

Quick Coupler

Not operationally checked

Rating:
Good

Blade Condition
Rating:
Good

Front Attachment
Hydraulic Quick Coupler, 28 in Digging Bucket, Hydraulic Thumb

RECONDITIONING

Glass: Cab door Glass missing, Upper cab window is cracked	\$2,000
Cab Door: Door frame damaged Pull handle is broken and frame is bent	\$4,500
Hand Rails: Cab entry hand rail damaged, On door frame	\$400
Auxiliary Hydraulic Plumbing: Operational, Thumb hose is leaking , drip	\$350
Total	\$7,250

UNIT SPECS

Customer	Auxilior Capital	Year	2024
Make	DEVELON	Model	DX55R-7

Unit Number

C22536

INSPECTION LOCATION



The Ironpeddlers Inc.
Duncan, SC 29334
803-608-9891

CURRENT LOCATION



The Ironpeddlers Inc.
Duncan, SC 29334
803-608-9891

VERSION HISTORY ?

✓ 08/28/2026