

# 2023 DOOSAN DX35Z

UNIT: DHKCEADYKN0001339

Price: \$0.00 USD

 [View Asset](#)



## GENERAL APPEARANCE

Year  
2023

Make  
Doosan

Model  
DX35Z

Unit Number  
DHKCEADYKN0001339

Serial  
DHKCEADYKN0001339

Paint  
No visible damage

Body Panels

Left Side Cover damaged, Right side cover damaged

Cab/Canopy Overhead Structural Framework  
No visible damage

Hand Rails  
Cab entry hand rail bent

Exterior Lights  
All lights operational

Serial Number / VIN  
DHKCEADYKN0001339

**SAFETY**

Travel Alarm  
Inoperable

Horn  
Operational

Seat Belts  
Operational

**CONTROL STATION**

Seat/Armrests  
No visible damage or missing components

Steering Controls  
Rating:  
Good

Hydraulic Controls  
Rating:  
Good

Drivetrain Controls  
Rating:  
Good

Dash Console  
Rating:  
Good

Warning Lights  
Operational

Gauges  
Operational

Limited Function Check (Control Station)  
The main components are in place and operational as noted.



Control Station  
Cab Details:, Cab Type Open Operator Station, Control Pattern Changer

Hour Meter / Odometer

555 hrs

Hour Meter /Odometer Usage Reading (Start)  
555 hrs

ENGINE

Starter  
Operational

Exhaust System  
No visible damage or missing components

Radiator  
Rating:  
Good

Oil Leaks  
No dripping leaks

Limited Function Check (Engine)  
The engine started and ran.

 Engine  
2022 US EPA Label

DRIVETRAIN

Left Drive Motor  
Rating:  
Good

Right Drive Motor  
Rating:  
Good

Left Final Drive  
Rating:  
Good

Right Final Drive  
Rating:  
Good

Limited Function Check (Drivetrain)  
The drivetrain was operational.

HYDRAULICS

Pumps (Hydraulics)  
Rating:  
Good

Valves  
Rating:  
Good

Hydraulic Tank

Rating:

Good

Hydraulic Control Pattern Changer

Rating:

Good

Hoses (Hydraulics)

Rating:

Good

Auxiliary Hydraulic Plumbing

Not operationally checked, End of stick

Swing Motor

Rating:

Good

Boom Swing Cylinders

Rating:

Good

Boom Lift Cylinder(s)

Some movement.

Rating:

Good

Stick Cylinder

Rating:

Good

Bucket Cylinder

Rating:

Good

Thumb Cylinder

Not operationally checked

Rating:

Good

Blade Lift Cylinder

Rating:

Good

Limited Function Check (Hydraulics)

The hydraulic system was operational.

## CHASSIS

Boom/Stick Details

Swing Boom, 5 ft Stick, Auxiliary Hydraulic Plumbing, Backfill Blade

Boom Condition

Rating:

Good

Stick Condition

Rating:

Good

Swing Tower Pivot

Rating:

Good

Boom Base Pin And Bushings

Rating:

Good

Pin And Bushings Boom To Stick

Rating:

Good

Pin And Bushings Stick To Bucket

Not operationally checked

Rating:

Good

Turntable Bearing

Rating:

Good

Bottom Covers

Rating:

Good

Limited Function Check (Chassis)

The main components were operational in a limited check.

## **RUBBER TRACK UNDERCARRIAGE**

Roller Frames

Rating:

Good

Grouser Height Measurement

Left side: 19 mm, Right side: 18 mm

Rubber Belt Drive Lugs

No visible damage

Track Tensioners

No visible damage

## **SPECIALTY**

Thumb

Hydraulic thumb

Rating:

Good

Blade Condition

Rating:

Good

Front Attachment

Hydraulic Thumb

RECONDITIONING

|                                      |         |
|--------------------------------------|---------|
| Left Side Cover: Damaged             | \$2,500 |
| Cab entry hand rail: Bent            | \$300   |
| Travel Alarm: Inoperable             | \$200   |
| Right side cover: Damaged            | \$2,500 |
| Boom Lift Cylinder(s): Some movement | \$3,500 |
| Total                                | \$9,000 |

UNIT SPECS

|             |                   |       |       |
|-------------|-------------------|-------|-------|
| Customer    | Wells Fargo (IMS) | Year  | 2023  |
| Make        | Doosan            | Model | DX35Z |
| Unit Number | DHKCEADYKN0001339 |       |       |

INSPECTION LOCATION

CURRENT LOCATION



**Wells Fargo (IMS)**  
Mooresville, AL 35649  
555-555-5555



**Wells Fargo (IMS)**  
Mooresville, AL 35649  
555-555-5555

**VERSION HISTORY** ?

✓ 07/28/2026