

2022 DOOSAN DX180LC-5

UNIT: DHKCEBBTPL0001527

Current Location: BOBCAT OF MAURY COUNTY - GDN, Columbia, TN 38401, 931-981-9909



UNIT SPECS

Customer	PNC Equipment Finance
Year	2022
Make	DOOSAN
Model	DX180LC-5
Unit Number	194087

RECONDITIONING

Mirrors: Broken and removed	\$300	Paint: Damage	\$3,000
Body Panels: Right rear door damaged	\$3,000	Steps: Tool box step bent	\$300
Exterior Lights: Cab light cover broken	\$250	Left Track Pads: has rubber inserts missing	\$1,500
Right Track Pads: Missing rubber inserts	\$1,500		
Total			\$9,850




























































































DOOSAN

Doosan Infracore Co., Ltd.
7-11 Hwasu Dong,
Dong-gu, Incheon, Korea

DESCRIPTION		DESIGNATION	
DC90HLC3-432-NC		QUICK COUPLER	
SERIAL NO.		DOOSAN NO.	
1012557			
MACHINE TYPE			
DOOSAN DX255 34MM DIPPER			
HYDRAULIC FLOW RATE			
5.9	GAL/MIN	26.6	LT/MIN
HYDRAULIC WORKING PRESSURE			
350	BAR	5000	PSI
CAPACITY			
1.1	SAE	SAE RATED	
ASSY LOCATION		LIFT EYE SWL	
1000		17000	
Y.C.M.		WEIGHT	
1000		17000	

Serial No. 827000082408B