


2019 DOOSAN DX225LC-5

Current Location: RB EVERETT, HALTOM CITY, TX 76117, 281-991-8161

UNIT: DHKCEBBUCK00026525



UNIT SPECS

Customer	PNC Equipment Finance
Year	2019
Make	DOOSAN
Model	DX225LC-5
Unit Number	170618

RECONDITIONING

Two Right side blind spot mirrors broken.	\$300	Cab Door: Door latch damaged Door frame damaged Door lock release on inside broken.	\$3,500
Rear View Camera: Camera inoperable, Right side camera not working. Rear one is operational.	\$2,000	Paint: Damage	\$3,000
Body Panels: Battery box damaged	\$3,500	Bucket Cutting Edge/Shanks/Teeth: Teeth worn, Teeth missing	\$400
Total			\$12,700






































WARNING
Cancer and Reproductive Harm
www.P65Warnings.ca.gov

DOOSAN Doosan Infracore

CAUTION-OIL SPECIFICATION

API CJ-4, ACEA E9

LOW ASH OIL IS REQUIRED

DOOSAN EMISSION CONTROL INFORMATION

This Engine complies with U.S. EPA and California regulation for 2019 nonroad diesel engines.

Emission Control System
: EGR, DOC, SCR, DFI, TC, CAC, ECM, DOS

Power Category : 130 ≤ kW ≤ 560

US Engine Family : KDICL05.0LEA

Engine Code : DLOS-LEE00

Manufactured by Doosan Infracore Co., Ltd.

Date Of Manufacture : 2019 / 07

Ultra Low Sulfur Fuel Only























































