

Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #15260646 - 2023 Doosan DX140LCR-7 Tracked Excavator



Item Details:

- Features: Air Conditioner, Straight Travel Pedal, Rear & Side View Cameras, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 10 in Stick, Auxiliary Hydraulic Plumbing, 40 in Digging Bucket, Hydraulic Thumb
- Meter Reading: 939 Hours
- Serial # : DHKCEBDUCN0001038
- Inspection Completed: 5/13/26

Shipping Details:

- Location Florida (Fort Myers-Cape Coral area)
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup


Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance		
Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		


Safety







Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Safety Lock Out/Stop	Operational	
Swing Brake	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	





Control Station

Item	Assessment	Photo
Control Station #1		
Control Station #2		
Seat/Armrests	No visible damage or missing components	
Glass	No visible damage or missing components	
Mirrors		
Cab Door	No visible damage or missing components	

Steering Controls	★★★★☆	
Hydraulic Controls	★★★★☆	
Drivetrain Controls	★★★★☆	
Dash Console	★★★★☆	
Engine Oil Pressure	No oil pressure indicator	
Warning Lights	Operational	
Gauges	Operational	
Rear View Camera	Camera operates as intended	





Hour Meter / Odometer	939 hrs	
Air Conditioner	Operational	
Heater	Operational	
Limited Function Check	<p>The main components are in place and operational as noted. Unit has a smart key. It has a dead battery. Unit is very hard to start.. weak signal from key needs battery.</p>	

Engine		
Item	Assessment	Photo
Engine	2022 US EPA Label, Requires Diesel Exhaust Fluid	
v2 Engine # 1		
Emission Label		
A/C Compressor	Operational	
Starter	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	







Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	
Engine - Left Side		
DEF / AdBlue Tank		
Limited Function Check	The engine started and ran.	







Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Left Drive Motor	★ ★ ★ ☆	 A photograph showing the left drive motor of a tracked vehicle, which is a large, dark, cylindrical component mounted on the track system.
Right Drive Motor	★ ★ ★ ☆	 A photograph showing the right drive motor of a tracked vehicle, similar to the left one, mounted on the track system.
Left Final Drive	★ ★ ★ ☆	 A close-up photograph of the left final drive, showing the internal gears and shafts of the drive mechanism.
Right Final Drive	★ ★ ★ ☆	 A close-up photograph of the right final drive, showing the internal gears and shafts of the drive mechanism.
Limited Function Check	The drivetrain was operational.	

Hydraulics





Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hydraulic Control Pattern Changer	★★★★☆	
Hoses (Hydraulics)	★★★★☆	
Auxiliary Hydraulic Plumbing	Operational, End of stick	
Swing Motor	★★★★☆	

Hydraulic Center Swivel	★★★★☆	
Boom Lift Cylinder(s)	★★★★☆	
Stick Cylinder	★★★★☆	
Bucket Cylinder	★★★★☆	
Thumb Cylinder	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Excavator_2 # 1		

Chassis







IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.








Item	Assessment	Photo
Chassis #1		
Chassis #2		
Chassis #3		
Chassis #4		
Boom Condition	★★★★☆	
Stick Condition	★★★★☆	







<p>Boom Base Pin and Bushings</p>	<p>★ ★ ★ ☆</p>	
<p>Pin and Bushings Boom to Stick</p>	<p>★ ★ ☆ ☆ Movement</p>	
<p>Pin and Bushings Stick to Bucket</p>	<p>★ ★ ☆ ☆ Movement</p>	
<p>Turntable Bearing</p>	<p>★ ★ ★ ☆</p>	
<p>Bottom Covers</p>	<p>★ ★ ★ ☆</p>	
<p>Limited Function Check</p>	<p>The main components were operational in a limited check.</p>	

Undercarriage

Undercarriage components photos (links, bushings, sprockets, idlers, rollers, grousers) are selected as representative. Bidders are encouraged to review photos using the zoom feature to judge condition in detail.






Item	Assessment	Photo
Track Link Brand	Other Doosan Other Doosan	
Left Roller Frame	★★★☆☆	
Left Track Tensioner	★★★☆☆	
Left Track Pads	★☆☆☆☆ 23.5 in Wide Worn damaged	
Left Grouser Height	Rubber Street Pads	
Left Track Links	94 mm	
Left Track Bushings	54 mm	
Left Carrier Rollers	1 carrier rollers #1 119 mm	

Left Bottom Rollers	7 Bottom Rollers #2 139 mm #3 139 mm #5 139 mm #6 139 mm #7 139 mm	
Left Idler	19 mm	
Left Sprocket	★★★★☆	
Right Roller Frame	★★★★☆	
Right Track Tensioner	★★★★☆	
Right Track Pads	★★★☆☆ 23.5 in Wide Worn damaged	
Right Grouser Height	Rubber Street Pads	
Right Track Links	94 mm	

Right Track Bushings	54 mm	
Right Carrier Rollers	1 Carrier Rollers #1 119 mm	
Right Bottom Rollers	7 Bottom Rollers: #2 139 mm #3 139 mm #5 139 mm #6 139 mm #7 139 mm	
Right Idler	19 mm	
Right Sprocket	★★★★☆	
Undercarriage #1		
Undercarriage #2		
Undercarriage #3		
Undercarriage #4		

Undercarriage #5



Specialty		
Item	Assessment	Photo
Specialty #1		
Specialty #2		
Excavator Bucket Condition	★★★★☆	
Bucket Cutting Edge/Shanks/Teeth	Wear	
Thumb	★★★★☆ Hydraulic thumb	

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved