



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #13749008 - Develon DX140LCR-7 Tracked Excavator



Item Details:

- Features: Air Conditioner, Control Pattern Changer, 2023 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 10 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, Hydraulic Quick Coupler, 42 in Digging Bucket, Hydraulic Thumb
- Meter Reading: 673 Miles
- Serial # : DHKCEBDUCP0001415
- Inspection Completed: 8/15/25

Shipping Details:

- Location Iowa (Iowa City area)
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup

Inspection Report


Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.


Inspection Ratings Key

★★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★★☆	Performs within the tolerances expected for age and type of item
★★★☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		


Serial Number / VIN	DHKCEBDUCP0001415	
CE Mark	No CE mark found	
Paint	No visible damage	
Body Panels	Left Side Cover damaged, Right rear door damaged, Right side cover damaged	
Steps	No visible damage or missing components	
Hand Rails	No visible damage or missing components	
Exterior Lights	All lights operational	
Excavator* # 1		

Excavator* # 2		
Excavator* # 3		
Excavator* # 4		
Excavator* # 5		
Excavator* # 6		
Excavator* # 7		
Excavator* # 8		

Excavator* # 9		
Excavator* # 10		

Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Safety Lock Out/Stop	Operational	
Swing Brake	Operational	
Current Safety Manual	Yes	
Current Operator/Maintenance Manual	Yes	
Excavator_2 # 1		

Control Station		
Item	Assessment	Photo
Control Station #1		
Control Station #2		
Control Station #3		
Control Station #4		
Control Station #5		
Seat/Armrests	No visible damage or missing components	

Glass	No visible damage or missing components	
Cab Door	No visible damage or missing components	
Steering Controls	★★★★☆	
Hydraulic Controls	★★★★☆	
Drivetrain Controls	★★★★☆	
Dash Console	★★★★☆	
Engine Oil Pressure	The fault indicator shuts off after the engine oil pressure rises.	

Warning Lights	Operational	
Gauges	Operational	
Rear View Camera	Camera operates as intended	
Grade Control Display	Grade Control display intact	
Grade Control Receiver/Controller	Grade control receiver intact	
Grade Control Antenna	Unable to test	
Hour Meter / Odometer	673 mi	
Air Conditioner	Inoperable, Will not blow cold air	
Heater	Operational	
Limited Function Check	The main components are in place and operational as noted.	


Engine		
Item	Assessment	Photo
Engine	2023 US EPA Label, Requires Diesel Exhaust Fluid	
v2 Engine # 1		
v2 Engine # 2		
Emission Label		
A/C Compressor	Operational	
Blow-by (subjective visual observation)	No noticeable vapor or pressure	
Starter	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	

Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	
Engine - Left Side		
Engine - Right Side		
DEF / AdBlue Tank		
Limited Function Check	The engine started and ran.	


Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Left Drive Motor	★★★★☆	
Right Drive Motor	★★★★☆	
Left Final Drive	★★★★☆	
Right Final Drive	★★★★☆	
Limited Function Check	The drivetrain was operational.	

Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hydraulic Control Pattern Changer	★★★★☆	
Hoses (Hydraulics)	★★★★☆	
Auxiliary Hydraulic Plumbing	Operational, Capped off, End of stick	
Swing Motor	★★★★☆	
Hydraulic Center Swivel	★★★★☆	

Boom Lift Cylinder(s)	★★★★☆	
Stick Cylinder	★★★★☆	
Bucket Cylinder	★★★★☆	
Thumb Cylinder	★★★★☆	
Blade Lift Cylinder	★★★★☆	
Limited Function Check	The hydraulic system was operational.	

Chassis		
Item	Assessment	Photo
Boom Condition	★★★★☆	
Stick Condition	★★★★☆	
Boom Base Pin and Bushings	★★★★☆	
Pin and Bushings Boom to Stick	★★★★☆	
Pin and Bushings Stick to Bucket		
Pins and Bushings Stick to Coupler	★★★★☆	

Turntable Bearing	☆☆☆☆	
Bottom Covers	☆☆☆☆	
Limited Function Check	The main components were operational in a limited check.	

Undercarriage



Undercarriage components photos (links, bushings, sprockets, idlers, rollers, grousers) are selected as representative. Bidders are encouraged to review photos using the zoom feature to judge condition in detail.

Item	Assessment	Photo
Left Roller Frame	★★★★☆	
Left Track Tensioner	★★★★☆	
Left Track Pads	★★★★☆ 23.5 in Wide Triple Grouser	
Left Grouser Height	25 mm	
Left Track Links	94 mm	
Left Track Bushings	52 mm	

Left Carrier Rollers	1 carrier rollers #1 117 mm	
Left Bottom Rollers	7 Bottom Rollers #1 139 mm #2 139 mm #3 139 mm #4 139 mm #5 139 mm #6 139 mm #7 139 mm	
Left Idler	18 mm	
Left Sprocket	★★★★☆	
Right Roller Frame	★★★★☆	
Right Track Tensioner	★★★★☆	
Right Track Pads	★★★★☆ 23.5 in Wide Triple Grouser	

Right Grouser Height	25 mm	
Right Track Links	94 mm	
Right Track Bushings	52 mm	
Right Carrier Rollers	1 Carrier Rollers #1 117 mm	
Right Bottom Rollers	7 Bottom Rollers: #1 139 mm #2 139 mm #3 139 mm #4 139 mm #5 139 mm #6 139 mm #7 139 mm	
Right Idler	19 mm	
Right Sprocket	★★★★☆	

Undercarriage #1		
Undercarriage #2		
Undercarriage #3		
Undercarriage #4		

Specialty		
Item	Assessment	Photo
Specialty #1		
Specialty #2		
Excavator Bucket Condition	★★★★☆ Coupler	
Bucket Cutting Edge/Shanks/Teeth	★★★☆☆ Plate welded across the teeth	
Quick Coupler	Not operationally checked	
Blade Condition	★★★★☆	

Blade Cutting Edge Condition		
Thumb	★★★★☆ Hydraulic thumb	

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet , Inc. © 2012 All Rights Reserved