

Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #15091758 - 2020 Doosan DL200-5 Wheel Loader



Item Details:

- Features: Enclosed Cab, Rear View Camera, 2020 US EPA Label, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 3 cyd 99 in Bucket
- Meter Reading: 895 Hours
- Serial # : DHKCWLBRCCL5050099
- Inspection Completed: 4/21/26

Shipping Details:

- Location Michigan (Grand Rapids-Muskegon-Holland area)
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.





Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

| Inspection Ratings Key | |
|------------------------|---|
| ★★★★ | Limited use or recently replaced. Free of visible wear or defects. |
| ★★★☆☆ | Performs within the tolerances expected for age and type of item |
| ★★☆☆☆ | Although performing, shows indication of needing repair or replacement |
| ★☆☆☆☆ | Needs immediate repair/replacement. Requires work if it is to perform as expected |

General Appearance

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

| Item | Assessment | Photo |
|-----------------------------|------------|--|
| Picture, Left Front Corner | |  |
| Picture, Left Rear Corner | |  |
| Picture, Right Rear Corner | |  |
| Picture, Right Front Corner | |  |

| | | |
|---------------------|---|--|
| Serial Number / VIN | DHKCWLBRCL5050099 |  |
| Paint | Damage, Rust |  |
| Body Panels | Left battery box heavy rust / corrosion, Right battery box heavy rust / corrosion | |
| Fenders | No visible damage or missing components. |  |
| Steps | No visible damage or missing components. |  |
| Hand Rails | No visible damage or missing components |  |
| Exterior Lights | All lights operational |  |

Wheel Loader* # 1



Wheel Loader* # 2



Wheel Loader* # 3





Wheel Loader* # 4









Wheel Loader* # 5












Safety







| Item | Assessment | Photo |
|-------------------------------------|-------------|--|
| Horn | Operational | |
| Seat Belts | Operational | |
| Safety Lock Out/Stop | Operational |  |
| Current Safety Manual | Yes | |
| Current Operator/Maintenance Manual | Yes | |
| Safety #1 | |  |




Control Station

| Item | Assessment | Photo |
|--------------------|---|--|
| Seat/Armrests | No visible damage or missing components |  |
| Glass | No visible damage or missing components |  |
| Mirrors | |  |
| Cab Doors | No visible damage or missing components |  |
| Steering Controls | ★★★★☆ |  |
| Hydraulic Controls | ★★★★☆ |  |







| | | |
|-----------------------|---|--|
| Drivetrain Controls | ★★★★☆ |  |
| Dash Console | ★★★★☆ |  |
| Engine Oil Pressure | The gauge registers in the operating range. |  |
| Warning Lights | Operational |  |
| Gauges | Operational |  |
| Rear View Camera | Camera operates as intended |  |
| Hour Meter / Odometer | 895 hrs |  |
| Air Conditioner | Operational | |





| | | |
|------------------------|--|--|
| Heater | Operational | |
| Limited Function Check | The main components are in place and operational as noted. | |
| Wheel Loader* # 1 | |  A photograph showing the interior of a wheel loader's operator cab. The view is from the driver's perspective, looking out through the windshield. A side mirror is visible on the left. The steering wheel and control levers are partially visible. The "IRON" logo is visible on the right side of the dashboard area. |
| Wheel Loader* # 2 | |  A photograph showing the exterior of a wheel loader. The machine is orange and black. The text "DL200" is visible on the side of the hood, and the "IRON" logo is on the front. The loader is parked outdoors with trees and a blue sky in the background. |

| Engine | | |
|--------------------|--|--|
| Item | Assessment | Photo |
| Engine | 2020 US EPA Label, Requires Diesel Exhaust Fluid | |
| Emission Label | |  |
| A/C Compressor | Operational |  |
| Starter | Operational | |
| Exhaust System | No visible damage or missing components |  |
| Radiator | ★★★★☆ |  |
| Oil Leaks | No dripping leaks |  |
| Engine - Left Side | |  |

| | | |
|------------------------|-----------------------------|--|
| Engine - Right Side | |  |
| DEF / AdBlue Tank | |  |
| Limited Function Check | The engine started and ran. | |
| Engine #1 | |  |







Drivetrain



| Item | Assessment | Photo |
|--------------------------|---------------------------------|--|
| Drive/Propel Motors | ★★★★☆ |  |
| Transfer Case / Drop Box | ★★★★☆ Operational |  |
| Front Drive Axle | ★★★★☆ |  |
| Rear Drive Axle | ★★★★☆ |  |
| Final Drives | ★★★★☆ |  |
| Limited Function Check | The drivetrain was operational. | |
| Drivetrain #1 | |  |

| | | |
|---------------|--|--|
| Drivetrain #2 | |  <p>A close-up photograph of a drivetrain component, likely a differential or axle assembly. The image shows various metal parts, including a yellow-painted component and a black shaft. The text "IRON" is visible in the bottom right corner of the image.</p> |
| Drivetrain #3 | |  <p>A photograph of a large black tire with a bright orange rim. The tire is mounted on a vehicle, and the text "IRON" is visible in the bottom right corner of the image.</p> |
| Drivetrain #4 | |  <p>A photograph of a large black tire with a bright orange rim. The tire is mounted on a vehicle, and the text "IRON" is visible in the bottom right corner of the image.</p> |
| Drivetrain #5 | |  <p>A photograph of a large black tire with a bright orange rim. The tire is mounted on a vehicle, and the text "IRON" is visible in the bottom right corner of the image.</p> |

Hydraulics






See photos for condition








| Item | Assessment | Photo |
|-----------------------|------------|--|
| Pumps (Hydraulics) | ★★★★☆ |  |
| Valves | ★★★★☆ |  |
| Hydraulic Tank | ★★★★☆ |  |
| Hoses (Hydraulics) | ★★★★☆ |  |
| Loader Lift Cylinders | ★★★★☆ |  |
| Bucket Tilt Cylinders | ★★★★☆ |  |




| | | |
|------------------------|---------------------------------------|--|
| Steering Cylinders | ☆☆☆☆ |  |
| Limited Function Check | The hydraulic system was operational. | |
| Hydraulics #1 | |  |

Chassis







IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

| Item | Assessment | Photo |
|---------------------------------|--|--|
| Articulating Center Pins | ★★★★☆ |  |
| Brake Type | Hydraulic | |
| Master Cylinder | ★★★★☆ |  |
| Brake Lines/Hoses | ★★★★☆ | |
| Park Brake | ★★★★☆ | |
| Limited Function Check - Brakes | The brake system functioned, stopping and holding the machine. | |
| Frame Condition | ★★★★☆ |  |
| Left Front Tire | ★★★☆☆ triangle TB516 20.5 R25 22/32" Tread Depth |  |
| Left Rear Tire | ★★★★☆ 27/32" Tread Depth |  |

| | | |
|---------------------------------------|--|--|
| <p>Right Rear Tire</p> | <p>★★★★☆ 27/32" Tread Depth</p> |  |
| <p>Right Front Tire</p> | <p>★★☆☆☆ 22/32" Tread Depth</p> |  |
| <p>Wheel Condition</p> | <p>No visible damage or missing components</p> |  |
| <p>Lift Arm Condition</p> | <p>★★★★☆</p> |  |
| <p>Chassis to Arm Pins</p> | <p>★★★★☆</p> |  |
| <p>Tilt Linkage</p> | <p>★★★★☆</p> |  |
| <p>Tilt Linkage Pins and Bushings</p> | <p>★★★★☆</p> |  |

| | | |
|----------------------------|--|--|
| Quick Coupler to Arms Pins | ☆☆☆☆ |  |
| Limited Function Check | The main chassis components were operational in a limited check. | |
| Chassis #1 | |  |
| Chassis #2 | |  |

Specialty

| Item | Assessment | Photo |
|----------------------------|--|--|
| Loader Bucket Condition | ★★☆☆☆ |  |
| Loader Bucket Cutting Edge | ★★☆☆☆ No visible damage or missing components |  |
| Loader Quick Coupler | ★★☆☆☆ Operational |  |
| Specialty #1 | |  |
| Specialty #2 | |  |
| Specialty #3 | |  |

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved