



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #15091759 - 2020 Doosan DL200-5 Wheel Loader



Item Details:

- Features: Enclosed Cab, Air Conditioner, Rear View Camera, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 3 cyd 99 in Bucket
- Meter Reading: 1,236 Hours
- Serial # : DHKCWLBRTK5050077
- Inspection Completed: 4/21/26

Shipping Details:

- Location Michigan (Grand Rapids-Muskegon-Holland area)
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	DHKCWLBR TK5050077	
Paint	Damage	
Body Panels	No visible damage or missing components.	
Fenders	No visible damage or missing components.	
Steps	No visible damage or missing components.	
Hand Rails	No visible damage or missing components	
Exterior Lights	All lights operational Switches would not operate lights	

Wheel Loader* # 1		
-------------------	--	---

Safety		
Item	Assessment	Photo
Horn	Operational	
Seat Belts	Operational	
Safety Lock Out/Stop	Operational	
Current Safety Manual	Yes	
Current Operator/Maintenance Manual	Yes	
Safety #1		

Control Station		
Item	Assessment	Photo
Seat/Armrests	No visible damage or missing components	
Glass	No visible damage or missing components	
Mirrors		
Cab Doors	No visible damage or missing components	
Steering Controls	★★★★☆	
Hydraulic Controls	★★★★☆	

Drivetrain Controls	★★★★☆	
Dash Console	★★★★☆	
Engine Oil Pressure	The fault indicator shuts off after the engine oil pressure rises.	
Warning Lights	Operational	
Gauges	Operational	
Rear View Camera	Camera operates as intended	
Hour Meter / Odometer	1236 hrs	
Air Conditioner	Operational	


Heater	Operational	
Limited Function Check	The main components are in place and operational as noted.	
Wheel Loader* # 1		
Wheel Loader* # 2		

Engine		
Item	Assessment	Photo
Engine	2019 US EPA Label, Requires Diesel Exhaust Fluid	
Emission Label		
A/C Compressor	Operational	
Starter	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Engine - Left Side		

Engine - Right Side		
DEF / AdBlue Tank		
Limited Function Check	The engine started and ran.	
Engine #1		

Drivetrain		
Item	Assessment	Photo
Drive/Propel Motors	★★★★☆	
Transfer Case / Drop Box	★★★★☆ Operational	
Front Drive Axle	★★★★☆	
Rear Drive Axle	★★★★☆	
Final Drives	★★★★☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		

Drivetrain #2		
Drivetrain #3		
Drivetrain #4		


Hydraulics		
See photos for condition		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses (Hydraulics)	★★★★☆	
Loader Lift Cylinders	★★★★☆	
Bucket Tilt Cylinders	★★★★☆	

Steering Cylinders	☆☆☆☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		

Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Articulating Center Pins	★★★★☆	
Brake Type	Hydraulic	
Master Cylinder	★★★★☆	
Brake Lines/Hoses	★★★★☆	
Park Brake	★★★★☆	
Limited Function Check - Brakes	The brake system functioned, stopping and holding the machine.	
Frame Condition	★★★★☆	
Left Front Tire	★★★☆☆ triangle TB516 20.5r25 23/32" Tread Depth	
Left Rear Tire	★★★★☆ 29/32" Tread Depth	

Right Rear Tire	 28/32" Tread Depth	
Right Front Tire	 26/32" Tread Depth	
Wheel Condition	No visible damage or missing components	
Lift Arm Condition		
Chassis to Arm Pins		
Tilt Linkage		
Tilt Linkage Pins and Bushings		

Quick Coupler to Arms Pins	★★★★☆	
Limited Function Check	The main chassis components were operational in a limited check.	
Chassis #1		
Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		

Specialty		
Item	Assessment	Photo
Loader Bucket Condition	★★★★☆	
Loader Bucket Cutting Edge	★★★★☆ No visible damage or missing components	
Loader Quick Coupler	★★★★☆ Operational	
Specialty #1		
Specialty #2		
Specialty #3		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved