

2021 DOOSAN DL250-5

UNIT: DHKCWLBSLL5050342

Current Location: Equipment Incorporated , Richland, MS 39218, 601-948-3272



UNIT SPECS

Customer PNC Equipment Finance

RECONDITIONING

Lift Arm Condition: Main frame where lift arm pins has bracket broken off on left side	\$500	Glass: Windshield cracked	\$1,500
Dash Console: Left side vent is broken	\$150	Paint: Damage	\$2,000
Body Panels: Left rear door damaged, Right rear door damaged,		Fenders: Left rear damaged, Right rear damaged	\$4,000
Left cab steps damaged, Right cab steps damaged	\$1,200	Exterior Lights: 2 Inoperable / damaged / missing 2 brackets for headlights are damaged	\$500
Hoses (Hydraulics): Bracket and hoses damaged to coupler	\$1,000	Left battery box damaged, Right battery box damaged	\$4,000
Loader Bucket Condition: Damaged on front lip	\$550	Loader Quick Coupler: Operational, Dripping leak where fittings are damaged	\$450
Forks: Tips have damage	\$650	Grille damaged	\$2,200
Total			\$18,700



























