



2021 DOOSAN DL250-5

UNIT: DHKCWLBSM5050414

Price: \$0.00 USD

[View Asset](#)





GENERAL APPEARANCE

Year
2021

Make
Doosan

Model
DL250-5

Unit Number
DHKCWLBSSM5050414

Pre-Operational Checks
Confirm Fluids Checked: Engine Coolant. Confirm Fluids Checked: Engine(s) Oil. Confirm Fluids Checked: Transmission Fluid. Confirm Fluids Checked: Hydraulic Fluid. Confirm Fluids Checked: Fuel Level

Paint
No visible damage

Body Panels
No visible damage or missing components.

Fenders
No visible damage or missing components.

Steps
Right cab steps damaged

Hand Rails
No visible damage or missing components

Exterior Lights
1 Inoperable / damaged / missing

Cab/Canopy Overhead Structural Framework
No visible damage

Serial Number / VIN
DHKCWLBSSM5050414

Serial Number
DHKCWLBSSM5050414

SAFETY

Travel Alarm
Operational

Horn
Operational

Seat Belts
Operational

CONTROL STATION

Seat/Armrests
No visible damage or missing components Left side glass/windshield.

Glass
Windshield shattered

Mirrors
Both outside side mirrors missing.

Cab Doors

No visible damage or missing components

Steering Controls

Rating:

Good

Hydraulic Controls

Rating:

Good

Drivetrain Controls

Rating:

Good

Dash Console

Rating:

Good

Warning Lights

Operational

Gauges

Operational

Rear View Camera

Camera operates as intended

Air Conditioner

Operational

Heater

Operational

Limited Function Check (Control Station)

The main components are in place and operational as noted.

Control Station

Cab Type, Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, Traction Control

Hour Meter /Odometer Usage Reading (Start)

2179 hrs

Hour Meter / Odometer

2180 hrs

ENGINE

A/C Compressor

Operational

Blow-by (Subjective Visual Observation)

No noticeable vapor or pressure

Starter

Operational

Exhaust System

No visible damage or missing components

Radiator
Rating:
Good

Limited Function Check (Engine)
The engine started and ran.

Engine
No US EPA Label Present Requires Diesel Exhaust Fluid

DRIVETRAIN

Transmission
Operational
Rating:
Good

Transfer Case / Drop Box
Operational
Rating:
Good

Front Drive Axle
Rating:
Good

Rear Drive Axle
Rating:
Good

Final Drives
Rating:
Good

Limited Function Check (Drivetrain)
The drivetrain was operational.

HYDRAULICS

Pumps (Hydraulics)
Rating:
Good

Valves
Rating:
Good

Hydraulic Tank
Rating:
Good

Hoses (Hydraulics)
Rating:
Good

Loader Lift Cylinders
Rating:
Good

Bucket Tilt Cylinders

Rating:

Good

Steering Cylinders

Rating:

Good

Limited Function Check (Hydraulics)

The hydraulic system was operational.

CHASSIS

Lift Arm Condition

Rating:

Good

Chassis To Arm Pins

Rating:

Good

Tilt Linkage

Rating:

Good

Tilt Linkage Pins And Bushings

Rating:

Good

Quick Coupler To Arms Pins

Rating:

Good

Limited Function Check (Chassis)

The main chassis components were operational in a limited check.

Articulating Center Pins

Rating:

Good

Brake Type

Hydraulic

Master Cylinder

Rating:

Good

Brake Lines/Hoses

Rating:

Good

Park Brake

Stopped from a slow roll

Rating:

Good

Limited Function Check - Brakes

The brake system functioned, stopping and holding the machine.

Frame Condition

Rating:
Good

Left Front Tire
Triangle TB516 20.5R25 26/32" Tread Depth
Rating:
Good

Left Rear Tire
Triangle TB516 20.5R25 26/32" Tread Depth
Rating:
Good

Right Rear Tire
Triangle TB516 20.5R25 25/32" Tread Depth
Rating:
Good

Right Front Tire
Triangle TB516 20.5R25 26/32" Tread Depth
Rating:
Good

Wheel Condition
No visible damage or missing components

SPECIALTY

Front Attachment
Hydraulic Coupler, 3.5 cyd 107 in Bucket

Loader Bucket Condition
Rating:
Good

Loader Bucket Cutting Edge
No visible damage or missing components
Rating:
Good

Loader Quick Coupler
Doosan Coupler, Operational
Rating:
Good

TIRE SIZE: 20.5R25

<u>26</u> _{/32}	<u> </u>	<u> </u>	<u>26</u> _{/32}
N/A	N/A	N/A	N/A
N/A			N/A

TIRE SIZE: 20.5R25

<u>26</u> _{/32}	<u> </u>	<u> </u>	<u>25</u> _{/32}
N/A	N/A	N/A	N/A
N/A			N/A

CHECK SECTION

RECONDITIONING

Windshield - shattered	\$1,500
Both exterior mirrors - missing	\$300
Right cab steps - damaged	\$600
1 Exterior Light - Inop	\$300
Total	\$2,700

UNIT SPECS

Customer Wells Fargo (IMS)

INSPECTION LOCATION

 Wells Fargo (IMS)
Orlando, FL 32810
555-555-5555

CURRENT LOCATION

 Wells Fargo (IMS)
Orlando, FL 32810
555-555-5555

VERSION HISTORY ?

✓ 09/25/2026