




UNIT SPECS

Customer PNC Equipment Finance

RECONDITIONING

Paint: Damage	\$2,500	Body Panels: Grille damaged	\$2,000
Fenders: Left front damaged, Left rear damaged, Right rear damaged	\$4,500	Left cab steps bent, Right cab steps bent	\$1,200
Exterior Lights: 1 Inoperable / damaged / missing	\$300	Loader Bucket Cutting Edge: Edge worn	\$550
Total			\$11,050



Doosan Infracore Co., Ltd.
489, Injung-Ro, Dong-gu,
Incheon, Korea

MODEL
제품명

DL220-5

PRODUCT IDENTIFICATION NUMBER
제품 식별 번호

>DHKCWLCXKM5050381<

MADE IN KOREA

950209-02977B







































