

2023 DEVELON DL280-7

UNIT: DHKCWLDKPP5050033

Price: \$0.00 USD



GENERAL APPEARANCE

Year
2023

Make
DEVELON

Model
DL280-7

Unit Number
1010311

Pre-Operational Checks
Confirm Fluids Checked: Engine Coolant. Confirm Fluids Checked: Engine(s) Oil. Confirm Fluids Checked: Transmission Fluid. Confirm Fluids Checked: Hydraulic Fluid. Confirm Fluids Checked: Fuel Level

Paint
Damage

Body Panels

Grille damaged, Part of the left rear door latch is missing.

Fenders

No visible damage or missing components.

Steps

Left cab steps damaged

Hand Rails

No visible damage or missing components

Exterior Lights

All lights operational

Cab/Canopy Overhead Structural Framework

No visible damage

Serial Number / VIN

DHKCWLDKPP5050033

Serial Number

DHKCWLDKPP5050033

SAFETY

Travel Alarm

Operational

Horn

Operational

Seat Belts

Operational

Safety Lock Out/Stop

Operational

Current Safety Manual

Yes

Current Operator/Maintenance Manual

Yes

CONTROL STATION

Seat/Armrests

Operator seat cover torn, There are small holes in the seat cover

Glass

No visible damage or missing components

Cab Doors

No visible damage or missing components

Steering Controls

Rating:

Good

Hydraulic Controls

Rating:
Good

Drivetrain Controls

Rating:
Good

Dash Console

Rating:
Good

Engine Oil Pressure

The fault indicator shuts off after the engine oil pressure rises.

Warning Lights

Operational, Check engine light stays on Exhaust after treatment, Maintenance/Service

Gauges

Operational

Rear View Camera

Camera operates as intended

Air Conditioner

Operational

Heater

Operational

Limited Function Check (Control Station)

The main components are in place and operational as noted.



Control Station

Cab Type, Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, Traction Control, Weigh system appears to be Develon On-Board Scale

Hour Meter /Odometer Usage Reading (Start)

2112 hrs

Hour Meter / Odometer

2113 mi

ENGINE

A/C Compressor

Operational

Blow-by (Subjective Visual Observation)

Minor



Starter

Operational

Exhaust System

No visible damage or missing components

Radiator

Rating:
Good

Oil Leaks
No dripping leaks

Fuel Leaks
No dripping leaks

Cooling System Leaks
No dripping leaks

Limited Function Check (Engine)
The engine started and ran.

 Engine
2023 US EPA Label, Requires Diesel Exhaust Fluid

DRIVETRAIN

Transmission
Operational
Rating:
Good

Front Drive Axle
Rating:
Good

Rear Drive Axle
Rating:
Good

Final Drives
Rating:
Good

Limited Function Check (Drivetrain)
The drivetrain was operational.

HYDRAULICS

Pumps (Hydraulics)
Rating:
Good

Valves
Rating:
Good

Hydraulic Tank
Rating:
Good

Hoses (Hydraulics)
Rating:
Good

Loader Lift Cylinders
Rating:
Good

Bucket Tilt Cylinders

Rating:

Good

Auxiliary Hydraulic Plumbing

Capped off, Not operationally checked, Front

Steering Cylinders

Rating:

Good

Limited Function Check (Hydraulics)

The hydraulic system was operational.

CHASSIS

Lift Arm Condition

Rating:

Good

Chassis To Arm Pins

Rating:

Good

Tilt Linkage

Rating:

Good

Tilt Linkage Pins And Bushings

Rating:

Good

Quick Coupler To Arms Pins

Rating:

Good

Limited Function Check (Chassis)

The main chassis components were operational in a limited check.

Articulating Center Pins

Rating:

Good

Brake Type

Hydraulic

Master Cylinder

Rating:

Good

Brake Lines/Hoses

Rating:

Good

Park Brake

Stopped from a slow roll

Rating:

Good

Limited Function Check - Brakes

The brake system functioned, stopping and holding the machine.

Frame Condition
Rating:
Very Good

Left Front Tire
Triangle TB516 20.5R25 27/32" Tread Depth There is a chunk missing from the sidewall
Rating:
Fair

Left Rear Tire
Triangle TB516 20.5R25 26/32" Tread Depth
Rating:
Good

Right Rear Tire
Triangle TB516 20.5T25 26/32" Tread Depth
Rating:
Good

Right Front Tire
Triangle TB516 20.5R25 26/32" Tread Depth Cracks in the sidewall
Rating:
Fair

Wheel Condition
No visible damage or missing components

SPECIALTY

Front Attachment
Front Attachment Details, Quick Coupler Type: Hydraulic Coupler, 108 in Bucket Type: Bucket

Loader Bucket Condition
Rating:
Good

Loader Bucket Cutting Edge
No visible damage or missing components
Rating:
Good

Loader Quick Coupler
Doosan Coupler, Not operational
Rating:
Fair

CHECK SECTION

RECONDITIONING

Left Front Tire: There is a chunk missing from the sidewall	\$3,500
Right Front Tire: Cracks in the sidewall	\$3,500
Seat/Armrests: Operator seat cover torn, There are small holes in the seat cover	\$450
Warning Lights: Operational, Check engine light stays on Exhaust after treatment, Maintenance/Service	\$4,500
Paint: Damage	\$2,500
Body Panels: Grille damaged	\$2,200
Left cab steps damaged	\$600
Loader Quick Coupler: Doosan Coupler, Not operational	\$1,000
Part of the left rear door latch is missing.	\$400
Total	\$18,650

UNIT SPECS

Customer	Auxilior Capital
----------	------------------

INSPECTION LOCATION



Central Power Systems & Services
Oklahoma City, OK 73127
405-324-2330

CURRENT LOCATION



Central Power Systems & Services
Oklahoma City, OK 73127
405-324-2330

VERSION HISTORY

✓ 08/04/2026