



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #14787771 - 2023 Develon DL250-7 High Lift Wheel Loader



Item Details:

- Features: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, 2023 US EPA Label, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 108 in Bucket
- Meter Reading: 2,350 Hours
- Serial # : DHKCWLDSHP5050367
- Inspection Completed: 3/27/26





Shipping Details:


- Location New York (Jefferson County)
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup








Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected


General Appearance		
IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	DHKCWLDSHP5050367	
Paint	Damage	
Body Panels	Right rear door damaged	
Fenders	Rust/ Corrosion Left, cab entry platform. DEF compartment/ Platform	
Steps	Left cab steps damaged	
Hand Rails	No visible damage or missing components	
Exterior Lights	All lights operational	
Wheel Loader* # 1		








Wheel Loader* # 2		
Wheel Loader* # 3		
Wheel Loader* # 4		
Wheel Loader* # 5		
Wheel Loader* # 6		
Wheel Loader* # 7		
Wheel Loader* # 8		







Wheel Loader* # 9		
Wheel Loader* # 10		
Wheel Loader* # 11		
Wheel Loader* # 12		
Wheel Loader* # 13		
Wheel Loader* # 14		
Wheel Loader* # 15		

Wheel Loader* # 16		
Wheel Loader* # 17		
Wheel Loader* # 18		
Wheel Loader* # 19		
Wheel Loader* # 20		







Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	Yes	
Safety #1		







Control Station		
Item	Assessment	Photo
Control Station #1		
Control Station #2		
Control Station #3		
Control Station #4		
Control Station #5		
Control Station #6		






Control Station #7		
Seat/Armrests	No visible damage or missing components	
Glass	No visible damage or missing components	
Mirrors		
Cab Doors	No visible damage or missing components	
Steering Controls	★★★★☆	
Hydraulic Controls	★★★★☆	







<p>Drivetrain Controls</p>	<p>★★★★☆</p>	
<p>Dash Console</p>	<p>★★★★★</p>	
<p>Engine Oil Pressure</p>	<p>The fault indicator shuts off after the engine oil pressure rises.</p>	
<p>Warning Lights</p>	<p>Operational</p>	
<p>Gauges</p>	<p>Operational</p>	
<p>Rear View Camera</p>	<p>Camera operates as intended</p>	
<p>Hour Meter / Odometer</p>	<p>2350 hrs</p>	




Air Conditioner	The ambient temperature is too cold to check	
Heater	Operational	
Limited Function Check	The main components are in place and operational as noted. Key fob battery is low	







Engine		
Item	Assessment	Photo
Engine	2023 US EPA Label, Requires Diesel Exhaust Fluid	
v2 Engine # 1		
v2 Engine # 2		
v2 Engine # 3		
v2 Engine # 4		
v2 Engine # 5		
v2 Engine # 6		







v2 Engine # 7		
Emission Label		
A/C Compressor	In place; ambient temperature too cold to check operation	
Blow-by (subjective visual observation)	No noticeable vapor or pressure	
Starter	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆ Unable to remove cap, bolt down cover	
Oil Leaks	No dripping leaks	







Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	
Engine - Left Side		
Engine - Right Side		
DEF / AdBlue Tank		
Limited Function Check	The engine started and ran.	






Drivetrain		
Item	Assessment	Photo
Transmission	★★☆☆ Operational	
Transfer Case / Drop Box	★★☆☆	
Front Drive Axle	★★☆☆	
Rear Drive Axle	★★☆☆	
Final Drives	★★☆☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		






Drivetrain #2		
Drivetrain #3		
Drivetrain #4		








<h2>Hydraulics</h2>		
See photos for condition		
Item	Assessment	Photo
Pumps (Hydraulics)	★ ★ ★ ☆	
Valves	★ ★ ★ ☆	
Hydraulic Tank	★ ★ ☆ ☆ Low fluid level, Just below sight glass	
Hoses (Hydraulics)	★ ★ ★ ☆	
Loader Lift Cylinders	★ ★ ★ ☆	
Bucket Tilt Cylinders	★ ★ ★ ☆	

Auxiliary Hydraulic Plumbing	Capped off, Not operationally checked, Front	
Steering Cylinders	★★★★☆	
Limited Function Check	The hydraulic system was operational. Heavy buildup up Silage, mud, and Manure prevented a more thorough inspection no leaks etc. were observed	
Hydraulics #1		
Hydraulics #2		
Hydraulics #3		
Hydraulics #4		

Hydraulics #5		
Hydraulics #6		
Hydraulics #7		
Hydraulics #8		
Hydraulics #9		
Hydraulics #10		








Chassis		
IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
Item	Assessment	Photo
Articulating Center Pins	★★★★☆	
Brake Type	Hydraulic	
Master Cylinder	★★★★☆	
Brake Lines/Hoses	★★★★☆	
Park Brake	★★★★☆ Stopped from a slow roll	
Limited Function Check - Brakes	The brake system functioned, stopping and holding the machine.	
Frame Condition	★★★★☆	
Left Front Tire	★★★☆☆ Triangle TB 516 20.5R25 18/32" Tread Depth ALL (4) TIRES ARE SAME BRAND, SIZE, MODEL	
Left Rear Tire	★★★☆☆ 20/32" Tread Depth	

Right Rear Tire	★★☆☆ 20/32" Tread Depth	
Right Front Tire	★★☆☆ 17/32" Tread Depth	
Wheel Condition	No visible damage or missing components	
Wheel Loader* # 1		
Wheel Loader* # 2		
Wheel Loader* # 3		
Wheel Loader* # 4		

Wheel Loader* # 5		
Lift Arm Condition	★★★★☆	
Chassis to Arm Pins	★★★★☆	
Tilt Linkage	★★★★☆	
Tilt Linkage Pins and Bushings	★★★★☆	
Bucket to Arm Pins		
Quick Coupler to Arms Pins	★★★☆☆ excessive play for hours used	

Limited Function Check	The main chassis components were operational in a limited check.	
------------------------	--	--

Specialty		
Item	Assessment	Photo
Specialty #1		
Specialty #2		
Specialty #3		
Specialty #4		
Specialty #5		
Specialty #6		

Specialty #7		
Specialty #8		
Specialty #9		
Specialty #10		
Loader Bucket Condition	★★★★☆	
Loader Bucket Cutting Edge	★☆☆☆ Edge missing No bolt on edge	
Loader Quick Coupler	★★★★☆ Doosan Coupler, Operational	

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved