

2023 DOOSAN DL220HL-7

UNIT: DHKCWLDVKN5050270

Price: \$0.00 USD

 [View Asset](#)



GENERAL APPEARANCE

Year
2023

Make
Doosan

Model
DL220HL-7

Pre-Operational Checks

Confirm Fluids Checked: Engine Coolant. Confirm Fluids Checked: Engine(s) Oil. Confirm Fluids Checked: Transmission Fluid. Confirm Fluids Checked: Hydraulic Fluid. Confirm Fluids Checked: Fuel Level

Paint
Damage

Fenders
No visible damage or missing components.

Steps

Left cab steps bent

Hand Rails

No visible damage or missing components

Exterior Lights

All lights operational

Cab/Canopy Overhead Structural Framework

No visible damage

Serial Number / VIN

DHKCWLDVKN5050270

Serial Number

DHKCWLDVKN5050270

MODEL DESCRIPTION

Model Description

High Lift

SAFETY

Travel Alarm

Operational

Horn

Operational

Seat Belts

Operational

Safety Lock Out/Stop

Operational

Current Safety Manual

Yes

Current Operator/Maintenance Manual

Yes

CONTROL STATION

Seat/Armrests

No visible damage or missing components

Glass

No visible damage or missing components

Cab Doors

No visible damage or missing components

Steering Controls

Rating:

Good

Hydraulic Controls

Rating:

Good

Drivetrain Controls

Rating:

Good

Dash Console

Rating:

Good

Engine Oil Pressure

The fault indicator shuts off after the engine oil pressure rises.

Warning Lights

Operational

Gauges

Operational

Rear View Camera

Camera operates as intended

Air Conditioner

Operational

Heater

Operational

Limited Function Check (Control Station)

The main components are in place and operational as noted.



Control Station

Cab Type, Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Traction Control

Hour Meter /Odometer Usage Reading (Start)

1616 hrs

Hour Meter / Odometer

1616 hrs

ENGINE

A/C Compressor

Operational

Blow-by (Subjective Visual Observation)

No noticeable vapor or pressure



Starter

Operational

Exhaust System

No visible damage or missing components

Radiator

Rating:

Good

Oil Leaks
No dripping leaks

Fuel Leaks
No dripping leaks

Cooling System Leaks
No dripping leaks

Limited Function Check (Engine)
The engine started and ran. Right side fender latch stuck shut. Can't open access door.

 Engine
2022 US EPA Label, Requires Diesel Exhaust Fluid

DRIVETRAIN

Transmission
Operational
Rating:
Good

Front Drive Axle
Rating:
Good

Rear Drive Axle
Rating:
Good

Limited Function Check (Drivetrain)
The drivetrain was operational.

HYDRAULICS

Pumps (Hydraulics)
Rating:
Good

Valves
Rating:
Good

Hydraulic Tank
Rating:
Good

Hoses (Hydraulics)
Rating:
Good

Loader Lift Cylinders
Rating:
Good

Bucket Tilt Cylinders
Rating:
Good

Auxiliary Hydraulic Plumbing
Not operationally checked, Front

Steering Cylinders
Rating:
Good

Limited Function Check (Hydraulics)
The hydraulic system was operational.

CHASSIS

Lift Arm Condition
Rating:
Good

Chassis To Arm Pins
Rating:
Good

Tilt Linkage
Rating:
Good

Tilt Linkage Pins And Bushings
Rating:
Good

Quick Coupler To Arms Pins
Rating:
Good

Limited Function Check (Chassis)
The main chassis components were operational in a limited check.

Articulating Center Pins
Rating:
Good

Brake Type
Hydraulic

Master Cylinder
Rating:
Good

Brake Lines/Hoses
Rating:
Good

Park Brake
Rating:
Good

Limited Function Check - Brakes
The brake system functioned, stopping and holding the machine.

Frame Condition
Rating:

Good

Left Front Tire
Triangle TB516 20.5R25 26/32" Tread Depth
Rating:
Good

Left Rear Tire
Triangle TB516 20.5R25 28/32" Tread Depth
Rating:
Good

Right Rear Tire
Triangle TB516 20.5R25 29/32" Tread Depth
Rating:
Good

Right Front Tire
Triangle TB516 20.5R25 26/32" Tread Depth
Rating:
Good

Wheel Condition
No visible damage or missing components

SPECIALTY

Front Attachment
Front Attachment Details, Auxiliary Hydraulics, Quick Coupler Type: Hydraulic Coupler

Loader Quick Coupler
Doosan Coupler, Operational
Rating:
Good

TIRE SIZE: 20.5R25

26/32			26/32
	N/A	N/A	
N/A			N/A
N/A			N/A

TIRE SIZE: 20.5R25

28/32

N/A

N/A

29/32

N/A
N/A

N/A
N/A

CHECK SECTION

RECONDITIONING

Paint: Damaged	\$2,000
----------------	---------

Left cab steps: bent	\$600
----------------------	-------

Right side fender latch: stuck shut and can't open access door	\$350
--	-------

Total	\$2,950
-------	---------

UNIT SPECS

Customer

Wells Fargo (IMS)

INSPECTION LOCATION

CURRENT LOCATION



Wells Fargo (IMS)
Mosinee, WI 54455
555-555-5555



Wells Fargo (IMS)
Mosinee, WI 54455
555-555-5555

VERSION HISTORY

✓ 05/13/2026
