

2023 HYUNDAI DL220 - 7

UNIT: DHKCWLDVKN5050284

[Download Reconditioning Printout](#)



UNIT SPECS

Customer Wells Fargo (IMS)

LOCATION

Wells Fargo (IMS)
Please call Pickup Support for location information
Coldwater, MI 49036

GENERAL APPEARANCE

Year
2023

Make
Hyundai

Model
DL220 - 7

Pre-Operational Checks

Confirm Fluids Checked: Engine Coolant. Confirm Fluids Checked: Engine(s) Oil. Confirm Fluids Checked: Hydraulic Fluid. Confirm Fluids Checked: Fuel Level. N/A: Transmission Fluid

Paint
No visible damage

Body Panels
No visible damage or missing components.

Fenders
No visible damage or missing components.

Steps
Left cab steps damaged, Right cab steps damaged

Hand Rails
No visible damage or missing components

Exterior Lights
All lights operational

Cab/Canopy Overhead Structural Framework
No visible damage

Serial Number / VIN
DHKCWLDVKN5050284

Serial Number
DHKCWLDVKN5050284

SAFETY

Travel Alarm
Operational

Horn
Operational

Seat Belts
Operational

Safety Lock Out/Stop
Operational

Current Safety Manual
No

Current Operator/Maintenance Manual
No

CONTROL STATION

Seat/Armrests
No visible damage or missing components

Glass
No visible damage or missing components

Cab Doors
Latch cover missing

Steering Controls
Rating:
Good

Hydraulic Controls
Rating:
Good

Drivetrain Controls
Rating:
Good

Dash Console
Rating:
Good

Engine Oil Pressure
No oil pressure indicator

Warning Lights
Operational

Gauges
Operational

Rear View Camera
Camera operates as intended

Air Conditioner
Operational

Heater
Operational

Limited Function Check (Control Station)
The main components are in place and operational as noted.



Control Station
Cab Type, Enclosed Cab, Air Conditioner, Rear View Camera

Hour Meter /Odometer Usage Reading (Start)
6060 hrs

Hour Meter / Odometer
6060 hrs

ENGINE

A/C Compressor
Operational

Blow-by (Subjective Visual Observation)
No noticeable vapor or pressure



Starter
Operational

Exhaust System
No visible damage or missing components

Radiator
Rating:
Good

Limited Function Check (Engine)
The engine started and ran.



Engine
US EPA Label not legible

DRIVETRAIN

Transmission
Operational
Rating:
Good

Transfer Case / Drop Box
Operational
Rating:
Good

Front Drive Axle
Rating:
Good

Rear Drive Axle
Rating:
Good

Final Drives
Rating:
Good

Limited Function Check (Drivetrain)
The drivetrain was operational.

HYDRAULICS

Pumps (Hydraulics)
Rating:
Good

Valves
Rating:
Good

Hydraulic Tank
Rating:
Good

Hoses (Hydraulics)
Rating:

Good

Loader Lift Cylinders

Rating:

Good

Bucket Tilt Cylinders

Rating:

Good

Steering Cylinders

Rating:

Good

Limited Function Check (Hydraulics)

The hydraulic system was operational.

CHASSIS

Lift Arm Condition

Rating:

Good

Chassis To Arm Pins

Rating:

Good

Tilt Linkage

Rating:

Good

Tilt Linkage Pins And Bushings

Rating:

Good

Quick Coupler To Arms Pins

Rating:

Good

Limited Function Check (Chassis)

The main chassis components were operational in a limited check.

Articulating Center Pins

Rating:

Good

Brake Type

Hydrostatic

Master Cylinder

Rating:

Good

Brake Lines/Hoses

Rating:

Good

Park Brake

Rating:

Good

Limited Function Check - Brakes

The brake system functioned, stopping and holding the machine.

Frame Condition

Rating:

Good

Left Front Tire

triangle tb516 20.5r25 20/32" Tread Depth

Rating:

Fair

Left Rear Tire

triangle tb516 20.5r25 19/32" Tread Depth

Rating:

Fair

Right Rear Tire

triangle tb516 20.tr25 21/32" Tread Depth

Rating:

Fair

Right Front Tire

triangle tb516 20.tr25 19/32" Tread Depth

Rating:

Fair

Wheel Condition

No visible damage or missing components

SPECIALTY

Front Attachment

Front Attachment Details, Quick Coupler Type: Hydraulic Coupler

Loader Quick Coupler

Not operationally checked

Rating:

Good

CHECK SECTION

TIRE SIZE: 20.5R25

20/₃₂

N/A

N/A

19/₃₂

N/A
N/A

N/A
N/A

TIRE SIZE: 20.5R25

19/₃₂

N/A

N/A

21/₃₂

N/A
N/A

N/A
N/A

RECONDITIONING

Cab Doors: Latch cover missing \$200

Left cab steps: damaged \$600

Right cab steps: damaged \$600

All 4 Tires: Worn \$28,000

Total \$29,400