

2020 DOOSAN DX225LL-5 LOG LOADER UNIT: DWGCEBCMCK1010178

Current Location: CASCADE TRADER, Hayden, ID 83835, 360-748-1182



UNIT SPECS

Customer PNC Equipment Finance

RECONDITIONING

Glass: Windshield cracked	\$1,500	Rear View Camera: Camera damaged	\$1,000
Body Panels: Hood damaged	\$2,000	Left track frame steps missing, Right track frame steps missing	\$1,200
Hand Rails: Tool box step hand rail missing	\$800	Exterior Lights: 4 Inoperable / damaged / missing	\$1,200
Horn: Inoperable	\$200	Safety Lock Out/Stop: Operational Cover missing	\$300
Total			\$8,200



























