

2020 DOOSAN DX300LL-5

UNIT: DWGCECBZCK1010183

Current Location: Cascade Trader, Hayden, ID 83835, 360-880-7534



UNIT SPECS

Customer PNC Equipment Finance

RECONDITIONING

Rear View Camera: Camera damaged \$1,500

Body Panels: Hood damaged \$2,500

Hand Rails: Tool box step hand rail bent \$800

Travel Alarm: Inoperable \$200

Cooling System Leaks: No dripping leaks Reservoir low \$250

Right track frame steps missing, Right rear step missing \$900

Exterior Lights: 1 Inoperable / damaged / missing \$200

Total

\$6,350





















