

2020 DOOSAN DX300LL-5 LOG LOADER

UNIT: DWGCECBZTK1010184

Current Location: FEENAUGHTY MACHINERY CO., Portland, OR 97218, 503-313-9220



UNIT SPECS

CustomerPNC Equipment Finance

RECONDITIONING

Paint: Damage	\$3,000	Body Panels: Right side cover damaged	\$2,500
Steps are missing on both tracks, bottom step to cab is dented	\$1,500	Cab entry hand rail damaged, Hand rails have been welded	\$1,600
Dripping leak, Valves on grapple are leaking	\$1,000	Grapple Rotation Motor: Dripping leak	\$2,500
right lockbox is dented	\$2,500		

Total

\$14,600

































































































































































