

Paint

No visible damage

Body Panels

No visible damage or missing components

Cab/Canopy Overhead Structural Framework

No visible damage

Steps

No visible damage or missing components

Hand Rails

No visible damage or missing components

Exterior Lights

All lights operational

Serial Number / VIN

DWGCECGBTP1010057

SAFETY

Travel Alarm

Operational

Horn

Operational

Seat Belts

Operational

Safety Lock Out/Stop

Operational

Swing Brake

Operational

Current Safety Manual

Yes

Current Operator/Maintenance Manual

Yes

CONTROL STATION

Seat/Armrests

No visible damage or missing components

Glass

No visible damage or missing components

Cab Door

No visible damage or missing components

Steering Controls

Rating:

Good

Hydraulic Controls

Rating:

Good

Drivetrain Controls

Rating:

Good

Dash Console

Rating:

Good

Engine Oil Pressure

No oil pressure indicator

Warning Lights

Operational, Smart key battery low warning

Gauges

Operational

Rear View Camera

Camera operates as intended

Grade Control Display

Grade Control display intact

Grade Control Receiver/Controller

Grade control receiver intact

Grade Control Antenna

Grade control Antenna intact

Air Conditioner

Operational

Heater

Operational

Limited Function Check (Control Station)

The main components are in place and operational as noted.



Control Station

Cab Details:, Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Surround View Cameras

Hour Meter / Odometer

1245 hrs

Hour Meter /Odometer Usage Reading (Start)

1245 hrs

ENGINE

A/C Compressor

Operational

Blow-by (Subjective Visual Observation)

No noticeable vapor or pressure



Starter

Operational

Exhaust System

No visible damage or missing components

Radiator

Rating:

Good

Oil Leaks

No dripping leaks Seepage near crankcase breather

Fuel Leaks

No dripping leaks

Cooling System Leaks

No dripping leaks

Limited Function Check (Engine)

The engine started and ran.



Engine

2023 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid

DRIVETRAIN

Left Drive Motor

Rating:

Good

Right Drive Motor

Rating:

Good

Left Final Drive

Rating:

Good

Right Final Drive

Rating:

Good

Limited Function Check (Drivetrain)

The drivetrain was operational.

HYDRAULICS

Pumps (Hydraulics)

Rating:

Good

Valves

Rating:

Good

Hydraulic Tank

Rating:

Good

Hydraulic Control Pattern Changer

Rating:

Good

Hoses (Hydraulics)

Rating:

Good

Auxiliary Hydraulic Plumbing

Capped off, Not operationally checked, End of stick

Swing Motor

Rating:

Good

Hydraulic Center Swivel

Rating:

Good

Boom Lift Cylinder(s)

Rating:

Good

Stick Cylinder

Rating:

Good

Bucket Cylinder

Rating:

Good

Limited Function Check (Hydraulics)

The hydraulic system was operational.

CHASSIS

Boom/Stick Details

Standard Boom, 10 ft 2 in Stick, Auxiliary Hydraulic Plumbing

Boom Condition

Rating:

Good

Stick Condition

Rating:

Good

Boom Base Pin And Bushings

Rating:

Good

Pin And Bushings Boom To Stick

Rating:

Good

Pins And Bushings Stick To Coupler

Rating:

Good

Turntable Bearing

Rating:
Good

Bottom Covers
Rating:
Good

Limited Function Check (Chassis)
The main components were operational in a limited check.

UNDERCARRIAGE

Track Link Brand
Other Doosan Other Doosan

Left Roller Frame
Rating:
Good

Left Track Tensioner
Rating:
Good

Left Track Pads
33.5 in Wide Triple Grouser Pad damaged
Rating:
Fair

Left Grouser Height
33 mm

Left Track Links
115 mm

Left Track Bushings
66 mm

Left Carrier Rollers
2 carrier rollers #1 141 mm #2 141 mm

Left Bottom Rollers
9 Bottom Rollers #1 CNM mm #2 CNM mm #3 CNM mm #4 180 mm #5 181 mm #6 178 mm #7 CNM mm #8 CNM mm #9
CNM mm Could not measure first three or last three rollers

Left Idler
23 mm

Left Sprocket
Rating:
Good

Right Roller Frame
Rating:
Good

Right Track Tensioner
Rating:
Good

Right Track Pads

33.5 in Wide Triple Grouser

Rating:
Good

Right Grouser Height
34 mm

Right Track Links
115 mm

Right Track Bushings
67 mm

Right Carrier Rollers
2 Carrier Rollers #1 141 mm #2 141 mm

Right Bottom Rollers
9 Bottom Rollers: #1 CNM mm #2 CNM mm #3 CNM mm #4 180 mm #5 180 mm #6 180 mm #7 CNM mm #8 CNM mm #9 CNM mm Could not measure first three or last three rollers

Right Idler
23 mm

Right Sprocket
Rating:
Good

SPECIALTY

Excavator Bucket Condition
Coupler
Rating:
Good

Bucket Cutting Edge/Shanks/Teeth
No visible damage or missing components
Rating:
Good

Quick Coupler
Operational
Rating:
Good

Front Attachment
Hydraulic Quick Coupler, 48 in Digging Bucket

RECONDITIONING

Left Track Pads: Pad damaged	\$500
Smart key battery low warning - Replace Batteries	\$1,500
Total	\$2,000

UNIT SPECS

Customer	Wells Fargo (IMS)	Year	2023
Make	Doosan	Model	DX350LCR-7
Unit Number	DWGCECGBTP1010057		

INSPECTION LOCATION

 Wells Fargo (IMS)
Webster, MA 00888
555-555-5555

CURRENT LOCATION

 Wells Fargo (IMS)
Webster, MA 00888
555-555-5555

VERSION HISTORY

✓ 07/14/2026