

Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #15260640 - 2023 Doosan DL280-7 Wheel Loader



Item Details:

- Features: Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Autoshift, 2022 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid, Auxiliary Hydraulics, Hydraulic Coupler, 3.5 cyd 108 in Bucket
- Meter Reading: 6,688 Miles
- Serial # : DWGCWLDKEN1010197
- Inspection Completed: 5/14/26

Shipping Details:

- Location Massachusetts (Worcester County)
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup





Inspection Report







Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	DWGCWLDKEN1010197	
Paint	Damage	
Body Panels	No visible damage or missing components.	
Fenders	No visible damage or missing components.	
Steps	No visible damage or missing components.	
Hand Rails	No visible damage or missing components	
Exterior Lights	All lights operational	

Wheel Loader* # 1



Wheel Loader* # 2



Wheel Loader* # 3



Wheel Loader* # 4



Wheel Loader* # 5




Wheel Loader* # 6









Wheel Loader* # 7










Safety







Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Safety Lock Out/Stop	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	








Control Station

Item	Assessment	Photo
Control Station #1		 A photograph showing the operator's seat and steering wheel area of a vehicle. The seat is grey and has "IRON" written on the backrest. The steering wheel is on the left side. The floor is metal and shows some wear.
Control Station #2		 A photograph showing the operator's feet and pedals. The operator is wearing black shoes. The floor is metal and shows some wear. The pedals are visible.
Control Station #3		 A photograph showing the dashboard and control panel. The dashboard is grey and has several buttons and a small display. The control panel is also grey and has several buttons. The floor is metal and shows some wear.
Control Station #4		 A close-up photograph of a digital display. The display shows "67.1" and "57.2 T" in red and white text. There are also some icons and a small map on the display. The display is mounted on a black frame.
Control Station #5		 A photograph showing the dashboard and control panel from a different angle. The dashboard is grey and has several buttons and a small display. The control panel is also grey and has several buttons. The floor is metal and shows some wear.
Seat/Armrests	No visible damage or missing components	 A close-up photograph of the seat and armrest area. The seat is grey and has a yellow patch on the side. The armrest is also grey and has a yellow patch on the side. The floor is metal and shows some wear.







Glass	No visible damage or missing components	
Mirrors		
Cab Doors	No visible damage or missing components	
Steering Controls	★★★★☆	
Hydraulic Controls	★★★★☆	
Drivetrain Controls	★★★★☆	
Dash Console	★★★★☆	

Engine Oil Pressure	No oil pressure indicator	
Warning Lights	Operational	
Gauges	Operational	
Rear View Camera	Camera operates as intended	
Hour Meter / Odometer	6688 mi	
Air Conditioner	Operational	
Heater	Operational	
Limited Function Check	The main components are in place and operational as noted.	

Engine		
Item	Assessment	Photo
Engine	2022 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid	
v2 Engine # 1		
v2 Engine # 2		
v2 Engine # 3		
Emission Label		
A/C Compressor	Operational	
Blow-by (subjective visual observation)	No noticeable vapor or pressure	
Starter	Operational	
Exhaust System	No visible damage or missing components	

Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	
Engine - Left Side		
Engine - Right Side		
DEF / AdBlue Tank		
Limited Function Check	The engine started and ran.	

Drivetrain

Item	Assessment	Photo
Transmission	★★★★☆ Operational	
Transfer Case / Drop Box	★★★★☆ Operational	
Front Drive Axle	★★★★☆	
Rear Drive Axle	★★★★☆	
Final Drives	★★★★☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		

Drivetrain #2









Drivetrain #3



Hydraulics






See photos for condition







Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★☆☆☆	
Hydraulic Tank	★★☆☆☆ Low fluid level	
Hoses (Hydraulics)	★★☆☆☆ Blow auxiliary line	
Loader Lift Cylinders	★★★★☆	
Bucket Tilt Cylinders	★★★★☆	








Auxiliary Hydraulic Plumbing	Front	
Steering Cylinders	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		
Hydraulics #3		
Hydraulics #4		
Hydraulics #5		

Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.






Item	Assessment	Photo
Articulating Center Pins	★★★★☆	
Brake Type	Hydraulic	
Master Cylinder	★★★★☆	
Brake Lines/Hoses	★★★★☆	
Park Brake	★★★★☆	
Limited Function Check - Brakes	The brake system functioned, stopping and holding the machine.	
Frame Condition	★★★★☆	
Left Front Tire	★★★★☆ Maxam MS330 20.5R25 38/32" Tread Depth	
Left Rear Tire	★★★★☆ Maxam MS330 20.5R25 38/32" Tread Depth	

Right Rear Tire	<p>★ ★ ★ ☆</p> <p>Maxam MS330 20.5R25 38/32" Tread Depth</p>	
Right Front Tire	<p>★ ★ ★ ☆</p> <p>Maxam MS330 20.5R25 37/32" Tread Depth</p>	
Wheel Condition	No visible damage or missing components	
Wheel Loader* # 1		
Wheel Loader* # 2		
Wheel Loader* # 3		
Wheel Loader* # 4		

Wheel Loader* # 5		
Wheel Loader* # 6		
Lift Arm Condition	★★★★☆	
Chassis to Arm Pins	★★★★☆	
Tilt Linkage	★★★★☆	
Tilt Linkage Pins and Bushings	★★★★☆	
Quick Coupler to Arms Pins	★★★★☆	

Limited Function Check	The main chassis components were operational in a limited check.	
------------------------	--	--

Specialty

Item	Assessment	Photo
Specialty #1		
Specialty #2		
Specialty #3		
Specialty #4		
Loader Bucket Condition	<p>★★★★☆</p>	
Loader Bucket Cutting Edge	<p>★★★★☆ No visible damage or missing components Edge slightly worn. Reversible not turned</p>	

Loader Quick Coupler



Not operational, Pins would not release



Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet , Inc. © 2012 All Rights Reserved