

2023 DOOSAN DL380-7

UNIT: DWGCWLDPKN1010122

Price: \$0.00 USD

 [View Asset](#)



GENERAL APPEARANCE

Year
2023

Make
Doosan

Model
DL380-7

Unit Number
DWGCWLDPKN1010122

Pre-Operational Checks

Confirm Fluids Checked: Engine Coolant. Confirm Fluids Checked: Engine(s) Oil. Confirm Fluids Checked: Transmission Fluid. Confirm Fluids Checked: Hydraulic Fluid. Confirm Fluids Checked: Fuel Level

Paint
Damage

Body Panels
Grille damaged

Fenders
Left rear damaged, Right front damaged, Right rear damaged

Steps
Left cab steps bent, Right cab steps damaged

Hand Rails
No visible damage or missing components

Exterior Lights
All lights operational

Cab/Canopy Overhead Structural Framework
No visible damage

Serial Number / VIN
DWGCWLDPKN1010122

Serial Number
DWGCWLDPKN1010122

SAFETY

Travel Alarm
Operational

Horn
Operational

Seat Belts
Operational

Current Safety Manual
No

Current Operator/Maintenance Manual
No

CONTROL STATION

Seat/Armrests
No visible damage or missing components

Glass
Windshield cracked

Cab Doors
No visible damage or missing components

Steering Controls
Rating:
Good

Hydraulic Controls
Rating:
Good

Drivetrain Controls

Rating:

Good

Dash Console

Rating:

Good

Engine Oil Pressure

The gauge registers in the operating range.

Warning Lights

Operational

Gauges

Operational

Rear View Camera

Display inoperable, Camera inoperable

Air Conditioner

Operational

Heater

Not operationally checked

Limited Function Check (Control Station)

The main components are in place and operational as noted.



Control Station

Cab Type, Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat

Hour Meter /Odometer Usage Reading (Start)

4796 mi

Hour Meter / Odometer

4796 hrs

ENGINE

A/C Compressor

Operational

Starter

Operational

Exhaust System

No visible damage or missing components

Radiator

Rating:

Good

Oil Leaks

No dripping leaks

Fuel Leaks

No dripping leaks

Cooling System Leaks
No dripping leaks

Limited Function Check (Engine)
The engine started and ran.

 Engine
No US EPA Label Present Requires Diesel Exhaust Fluid

DRIVETRAIN

Transmission
Operational
Rating:
Good

Transfer Case / Drop Box
Operational
Rating:
Good

Front Drive Axle
Rating:
Good

Rear Drive Axle
Rating:
Good

Final Drives
Rating:
Good

Limited Function Check (Drivetrain)
The drivetrain was operational.

HYDRAULICS

Pumps (Hydraulics)
Rating:
Good

Valves
Rating:
Good

Hydraulic Tank
Rating:
Good

Hoses (Hydraulics)
Rating:
Good

Loader Lift Cylinders
Rating:
Good

Bucket Tilt Cylinders

Rating:
Good

Auxiliary Hydraulic Plumbing
Not operationally checked, Front

Multi Purpose Bucket Cylinders
Rating:
Good

Steering Cylinders
Rating:
Good

Limited Function Check (Hydraulics)
The hydraulic system was operational.

CHASSIS

Lift Arm Condition
Rating:
Good

Chassis To Arm Pins
Rating:
Good

Tilt Linkage
Rating:
Good

Tilt Linkage Pins And Bushings
Rating:
Good

Bucket To Arm Pins
Rating:
Good

Quick Coupler To Arms Pins
Rating:
Good

Limited Function Check (Chassis)
The main chassis components were operational in a limited check.

Articulating Center Pins
Rating:
Good

Brake Type
Hydraulic

Master Cylinder
Rating:
Good

Brake Lines/Hoses
Rating:
Good

Park Brake

Rating:

Good

Limited Function Check - Brakes

The brake system functioned, stopping and holding the machine.

Frame Condition

Rating:

Good

Left Front Tire

Triangle Tb 516 all steel tubeless 23.5r25 33/32" Tread Depth

Rating:

Good

Left Rear Tire

Triangle Tb516 23.5r25 34/32" Tread Depth

Rating:

Good

Right Rear Tire

Triangle Tb516 23.5r25 33/32" Tread Depth

Rating:

Good

Right Front Tire

Triangle Tb516 23.5r25 33/32" Tread Depth

Rating:

Good

Wheel Condition

No visible damage or missing components

SPECIALTY

Front Attachment

Front Attachment Details, Quick Coupler Type: Hydraulic Coupler, 5 cyd 117 in Bucket Type: Bucket

Loader Bucket Condition

Rating:

Good

Loader Bucket Cutting Edge

No visible damage or missing components

Rating:

Good

Loader Quick Coupler

Rating:

Good

TIRE SIZE: 23.5R25

33/32

N/A

N/A

33/32

N/A
N/A

N/A
N/A

TIRE SIZE: 23.5R25

34/32

N/A

N/A

33/32

N/A
N/A

N/A
N/A

CHECK SECTION

RECONDITIONING

Windshield: cracked	\$1,500
---------------------	---------

Rear View Camera: Display inoperable and Camera inoperable	\$1,000
--	---------

Paint: Damaged	\$2,500
----------------	---------

Grille: damaged	\$2,200
-----------------	---------

Both Rear and Right Front Fenders: damaged	\$3,500
--	---------

Left cab steps: bent	\$600
Right cab steps: damaged	\$600
Total	\$11,900

UNIT SPECS

Customer	Wells Fargo (IMS)
----------	-------------------

INSPECTION LOCATION



Wells Fargo (IMS)
Whichita, KS 67217
555-555-5555

CURRENT LOCATION



Wells Fargo (IMS)
Whichita, KS 67217
555-555-5555

VERSION HISTORY ?

✓ 07/29/2026
