

# 2022 DOOSAN DL480-7

UNIT: DWGCWLDRKM1010024

Current Location: BEST LINE EQUIPMENT, Allentown, PA 18104, 570-279-6768



## UNIT SPECS

Customer PNC Equipment Finance

## RECONDITIONING

Left Front Tire: Triangle TB516 26.5 R25 27/32" Tread \$8,000  
Depth Tires have cracks in them

Body Panels: Left rear door damaged \$2,500



Loader Bucket Cutting Edge: Edge worn Edge \$650  
damaged Edge missing

**Total** \$19,750

Left Rear Tire: Triangle TB 516 26.5 R 25 29/32" \$8,000  
Tread Depth Tires have dry cracking

Loader Bucket Condition: There is cracked metal on \$600  
the underside of the bucket towards the front









































SCANIA  
EMISSION CONTROL INFORMATION  
MANUFACTURER: SCANIA CV AB  
ENGINE FAMILY: LY9XL12.7DAA  
POWER CATEGORY: 130 ≤ kW ≤ 560  
ENGINE DISPLACEMENT: 12.7 L  
DATE OF MANUFACTURE: 11-2020  
EMISSION-CONTROL SYSTEM:  
DOI, ECM, TC, CAC, EGR, SPL, DOC, SCR, AMOX  
ULTRA LOW SULFUR FUEL ONLY  
THIS ENGINE COMPLIES WITH U.S. EPA NONROAD  
REGULATIONS FOR 2020 DIESEL ENGINES.

