

2023 DEVELON DL420-7

UNIT: DWGCWLECAN1010333

Price: \$0.00 USD



GENERAL APPEARANCE

Year
2023

Make
DEVELON

Model
DL420-7

Unit Number
1008640

Pre-Operational Checks

Confirm Fluids Checked: Engine Coolant. Confirm Fluids Checked: Engine(s) Oil. Confirm Fluids Checked: Transmission Fluid. Confirm Fluids Checked: Hydraulic Fluid. Confirm Fluids Checked: Fuel Level

Paint
No visible damage

Body Panels

Grille damaged

Fenders

Right front damaged, Right rear damaged

Steps

Left cab steps bent, Right cab steps bent

Hand Rails

No visible damage or missing components

Exterior Lights

rear right damaged Inoperable / damaged / missing

Cab/Canopy Overhead Structural Framework

No visible damage

Serial Number / VIN

DWGCWLECAN1010333

Serial Number

DWGCWLECAN1010333

SAFETY

Travel Alarm

Operational

Horn

Operational

Seat Belts

Operational

Safety Lock Out/Stop

Operational

Current Safety Manual

No

Current Operator/Maintenance Manual

No

CONTROL STATION

Seat/Armrests

No visible damage or missing components

Glass

No visible damage or missing components

Cab Doors

No visible damage or missing components

Steering Controls

Rating:

Good

Hydraulic Controls

Rating:
Good

Drivetrain Controls

Rating:
Good

Dash Console

Rating:
Good

Engine Oil Pressure

No oil pressure indicator

Warning Lights

Operational

Gauges

Operational

Rear View Camera

Camera operates as intended

Air Conditioner

Inoperable

Heater

Operational

Limited Function Check (Control Station)

The main components are in place and operational as noted.

Control Station

Cab Type, Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat

Hour Meter /Odometer Usage Reading (Start)

3180.5 hrs

Hour Meter / Odometer

3181 hrs

ENGINE

A/C Compressor

Compressor will not engage

Blow-by (Subjective Visual Observation)

No noticeable vapor or pressure

Starter

Operational

Exhaust System

No visible damage or missing components

Radiator

Rating:
Good

Oil Leaks

No dripping leaks

Fuel Leaks

No dripping leaks

Cooling System Leaks

No dripping leaks

Limited Function Check (Engine)

The engine started and ran.

Emission Status

Tier 4

Engine

No US EPA Label Present

DRIVETRAIN

Transmission

Operational

Rating:

Good

Transfer Case / Drop Box

Operational

Rating:

Good

Front Drive Axle

Rating:

Good

Rear Drive Axle

Rating:

Good

Limited Function Check (Drivetrain)

The drivetrain was operational.

HYDRAULICS

Pumps (Hydraulics)

Rating:

Good

Valves

Rating:

Good

Hydraulic Tank

Rating:

Good

Hoses (Hydraulics)

Rating:

Good

Loader Lift Cylinders

Rating:
Good

Bucket Tilt Cylinders

Rating:
Good

Auxiliary Hydraulic Plumbing

Not operationally checked, Front

Steering Cylinders

Rating:
Good

Limited Function Check (Hydraulics)

The hydraulic system was operational.

CHASSIS

Lift Arm Condition

Rating:
Good

Chassis To Arm Pins

Rating:
Good

Tilt Linkage

Rating:
Good

Tilt Linkage Pins And Bushings

Rating:
Good

Quick Coupler To Arms Pins

Rating:
Good

Limited Function Check (Chassis)

The main chassis components were operational in a limited check.

Articulating Center Pins

Rating:
Good

Brake Type

Hydraulic

Master Cylinder

Rating:
Good

Brake Lines/Hoses

Rating:
Good

Park Brake

Rating:
Good

Limited Function Check - Brakes
The service brakes were operational.

Frame Condition
Rating:
Good

Left Front Tire
Triangle TB 516 26.5 R 25 19/32" Tread Depth
Rating:
Fair

Left Rear Tire
Triangle TB516 26.5 R 25 18/32" Tread Depth
Rating:
Fair

Right Rear Tire
Triangle TB516 26.5 R 25 20/32" Tread Depth
Rating:
Fair

Right Front Tire
Triangle TB516 26.5 R 25 19/32" Tread Depth
Rating:
Fair

Wheel Condition
No visible damage or missing components

SPECIALTY

Front Attachment
128 in Bucket

Loader Bucket Condition
Rating:
Good

Loader Bucket Cutting Edge
Edge worn Edge damaged
Rating:
Fair

Loader Quick Coupler
Not operationally checked

LOGISTICS INFORMATION

Shipping Dimensions
33 ft Long x 11 ft Wide x 12 ft Tall

General Shipping Information
Yes: Does this Unit Run? Yes: If self propelled, does the unit travel? No: Is the unit taller than 12'? Yes: Is the unit wider than 8'6"? Yes: Inflated Tires - item can roll? No: Noticeable fluid leaks?

Road Related Shipping Info
Yes: Lights Operate? Yes: Brakes Operate? Yes: Tires OK?

CHECK SECTION

RECONDITIONING

Air Conditioner: Inoperable	\$2,500
Body Panels: Grille damaged	\$2,500
Fenders: Right front damaged, Right rear damaged	\$3,000
Left cab steps bent, Right cab steps bent	\$1,200
Exterior Lights: rear right damaged Inoperable / damaged / missing	\$300
Loader Bucket Cutting Edge: Edge worn Edge damaged	\$550
4 Tires Past 50% Worn	\$18,000
Total	\$28,050

UNIT SPECS

Customer

Auxilior Capital

INSPECTION LOCATION



Central Power

Midland, TX 79706

432-248-8344

CURRENT LOCATION



Central Power

Midland, TX 79706

432-248-8344

VERSION HISTORY ?

✓ 10/07/2026