2020 DOOSAN DX140LC-5

UNIT: L0002292

Current Location: Best Line Equipment , Allentown, PA 18104, 484-223-3814





UNIT SPECS

Customer	PNC Equipment Finance
Year	2020
Make	Doosan
Model	DX140LC-5
Unit Number	186041

RECONDITIONING

Pins And Bushings Stick To Coupler: Heavy movement	$3,500
Body Panels: Right rear door damaged	$3,000
Exterior Lights: 3 Inoperable / damaged / missing	$900
Left/Right Track Pads: Damaged/missing pad inserts.	$1,500
Paint: Damaged	$2,500
Steps: Tool box step bent	$300
Hoses (Hydraulics): Bent hard lines.	$750

Total $12,450



DOOSAN
DX140LC
DEVELON


DOOSAN
DX140LC
XTREME


DOOSAN
Doosan Infracore Co., Ltd.
489, Injung-Ro, Dong-gu,
Incheon, Korea
MODEL
제품명
DX140LC-5
PRODUCT IDENTIFICATION NUMBER
제품 식별 번호
>DHKCEBBRTL0002292<
MADE IN KOREA
950209-02977B


DOOSAN
DX140LC


DX140LC
BEST LINE




DX140LC








DX140LC


DX140LC


DOOSAN
DX140LC
660SJ
BEST LINE




DOOSAN
DX140LC
BEST LINE


DOOSAN
DX140LC


DOOSAN


BEST LINE
EQUIPMENT








DOOSAN



