2021 DOOSAN DL250

UNIT: DHKCWLBSSM5050381

Current Location: Equipment Inc, Richland, MS 39218, 601-573-7839





UNIT SPECS

Customer	PNC Equipment Finance

RECONDITIONING

Park Brake: Inoperable	$750	**Right Rear Tire: Past 50% Worn, Has cuts**	$3,500
Glass: Windshield shattered, Right cab door shattered	$3,000	**Cab Doors: Left door seal damaged**	$300
Air Conditioner: Inoperable	$2,500	**Paint: Damage/Rust**	$3,500
Body Panels: Left rear door damaged, Right rear door damaged,	$6,000	**Fenders: Left front damaged, Left rear damaged, Right front damaged**	$4,500
Left cab steps damaged, Right cab steps damaged	$1,200	**Exterior Lights: 2 Inoperable / damaged / missing**	$600
Valves: Dripping leak	$2,000	**Horn: Inoperable**	$200
Total			$28,050


DL250


DOOSAN
DL250


DOOSAN
Doosan Infracore Co., Ltd.
489, Injung-Ro, Dong-gu,
Incheon, Korea
MODEL
제품명
DL250-5
PRODUCT IDENTIFICATION NUMBER
제품 식별 번호
MADE IN KOREA
950209-02977B


DOOSAN
DL250


DOOSAN
EM-Master


DOOSAN
CONNECT


DL250
DOOSAN


DOOSAN


SAN
DOOSAN
CONNECT


DL250
OOSAN
CONNECT




DL250


DL250





DL250




DOOSAN


DOOSAN


EVELON




DOOSAN




F
N
R
1
2
3


20
30
10
40
50
P N
800