2023 DOOSAN DX350LC-7

UNIT: DWGCECGTPN1010230

Price: $0.00 USD

View Asset



















































HOURS
DOOSAN

DOOSAN































DOOSAN






































DOOSAN



















GENERAL APPEARANCE

Year
2023

Make
Doosan

Model
DX350LC-7

Unit Number
DWGCECGTPN1010230

Serial
DWGCECGTPN1010230

CE Mark
No CE mark found

Pre-Operational Checks
Confirm Fluids Checked: Engine Coolant. Confirm Fluids Checked: Engine(s) Oil. N/A: Transmission Fluid. Confirm Fluids Checked: Hydraulic Fluid. Confirm Fluids Checked: Fuel Level

Paint
Damaged

Body Panels
Right rear door damaged

Cab/Canopy Overhead Structural Framework
No visible damage

Steps
Left track frame steps bent, Right track frame steps bent

Hand Rails
No visible damage or missing components

Exterior Lights
All lights operational

Serial Number / VIN
DWGCECGTPN1010230

SAFETY

Travel Alarm
Operational

Horn
Operational

Seat Belts
Operational

Safety Lock Out/Stop
Operational

Swing Brake
Operational

Current Safety Manual
Yes

Current Operator/Maintenance Manual
Yes

CONTROL STATION

Seat/Armrests
No visible damage or missing components

Glass
Windshield cracked

Cab Door
No visible damage or missing components

Steering Controls
Rating:
Good

Hydraulic Controls
Rating:
Good

Drivetrain Controls
Rating:
Good

Dash Console
Rating:
Good

Engine Oil Pressure
No oil pressure indicator

Warning Lights
Operational

Gauges
Operational

Rear View Camera

Camera operates as intended

Air Conditioner
Operational

Heater
Operational

Limited Function Check (Control Station)
The main components are in place and operational as noted.

Control Station
Cab Details:, Air Conditioner, Straight Travel Pedal, Control Pattern Changer, Rear & Side View Cameras

Hour Meter / Odometer
2641 hrs

Hour Meter /Odometer Usage Reading (Start)
2640.5 hrs

ENGINE

A/C Compressor
Operational

Blow-by (Subjective Visual Observation)
No noticeable vapor or pressure

Starter
Operational

Exhaust System
No visible damage or missing components

Radiator
Rating:
Good

Oil Leaks
No dripping leaks

Fuel Leaks
No dripping leaks

Cooling System Leaks
No dripping leaks

Limited Function Check (Engine)
The engine started and ran.

Engine
2022 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid

DRIVETRAIN

Left Drive Motor
Rating:
Good

Right Drive Motor
Rating:
Good

Left Final Drive
Rating:
Good

Right Final Drive
Rating:
Good

Limited Function Check (Drivetrain)
The drivetrain was operational.

HYDRAULICS

Pumps (Hydraulics)
Rating:
Good

Valves
Rating:
Good

Hydraulic Tank
Low fluid level
Rating:
Fair

Hydraulic Control Pattern Changer
Rating:
Good

Hoses (Hydraulics)
Rating:
Good

Auxiliary Hydraulic Plumbing
Not operationally checked, End of stick

Swing Motor
Rating:
Good

Hydraulic Center Swivel
Rating:
Good

Boom Lift Cylinder(s)
Rating:
Good

Stick Cylinder
Rating:
Good

Bucket Cylinder
Rating:
Good

Limited Function Check (Hydraulics)
The hydraulic system was operational.

CHASSIS

Boom/Stick Details
Standard Boom, 10 ft 6 in Stick, Auxiliary Hydraulic Plumbing

Boom Condition
Rating:
Good

Stick Condition
Rating:
Good

Boom Base Pin And Bushings
Rating:
Good

Pin And Bushings Boom To Stick
Rating:
Good

Pins And Bushings Stick To Coupler
Rating:
Good

Turntable Bearing
Rating:
Good

Bottom Covers
Rating:
Good

Limited Function Check (Chassis)
The main components were operational in a limited check.

UNDERCARRIAGE

Track Link Brand
Other Doosan Other Doosan

Left Roller Frame
Rating:
Good

Left Track Tensioner
Rating:
Good

Left Track Pads
31.5 in Wide Triple Grouser
Rating:
Good

Left Grouser Height

33 mm

Left Track Links
115 mm

Left Track Bushings
59 mm

Left Carrier Rollers
2 carrier rollers #1 140 mm #2 140 mm

Left Bottom Rollers
9 Bottom Rollers #1 177 mm #2 CNM mm #3 CNM mm #4 178 mm #5 179 mm #6 180 mm #7 CNM mm #8 CNM mm #9 179 mm

Left Idler
24 mm

Left Sprocket
Rating:
Good

Right Roller Frame
Rating:
Good

Right Track Tensioner
Rating:
Good

Right Track Pads
31.5 in Wide Triple Grouser
Rating:
Good

Right Grouser Height
34 mm

Right Track Links
115 mm

Right Track Bushings
66 mm

Right Carrier Rollers
2 Carrier Rollers #1 140 mm #2 141 mm

Right Bottom Rollers
9 Bottom Rollers: #1 175 mm #2 CNM mm #3 CNM mm #4 174 mm #5 175 mm #6 179 mm #7 CNM mm #8 CNM mm #9 175 mm

Right Idler
25 mm

Right Sprocket
Rating:
Good

SPECIALTY

Excavator Bucket Condition
Rating:
Good

Bucket Cutting Edge/Shanks/Teeth
No visible damage or missing components
Rating:
Good

Quick Coupler
Operational
Rating:
Good

Front Attachment
Hydraulic Quick Coupler, 54 in Digging Bucket

RECONDITIONING

Windshield: cracked	$1,500
Paint: Damaged	$2,500
Right rear door: Damaged	$3,000
Left track frame steps: bent	$600
Right track frame steps: bent	$600
Hydraulic Tank: Low fluid level	$350
Total	**$8,550**

UNIT SPECS

Customer	Wells Fargo (IMS)	**Year**	2023
Make	Doosan	**Model**	DX350LC-7
Unit Number	DWGCECGTPN1010230		

INSPECTION LOCATION

Wells Fargo (IMS)
Webster, MA 00888
555-555-5555

CURRENT LOCATION

Wells Fargo (IMS)
Webster, MA 00888
555-555-5555

VERSION HISTORY

✔ 09/04/2026