2021 DOOSAN DL550-5

UNIT: DWGCWLBLCL1010288





UNIT SPECS

Customer	PNC Equipment Finance

LOCATION

PNC Equipment Finance
4800 NE Columbia Blvd
Portland, OR 97218

GENERAL APPEARANCE

Year
2021

Make
Doosan

Model
DL550-5

Unit Number
185024

Paint
Damage

Body Panels
Right side cover damaged, Grille damaged

Fenders
Left front damaged, Left rear damaged, Right front damaged, Right rear damaged

Steps
Left rear step bent.

Hand Rails
Right front hand rails bent

Exterior Lights
4 Inoperable / damaged / missing

Cab/Canopy Overhead Structural Framework
No visible damage

Serial Number / VIN
DWGCWLBLCL1010288

Serial Number
DWGCWLBLCL1010288

SAFETY

Travel Alarm
Operational

Horn
Operational

Seat Belts
Operational

Current Safety Manual
Yes

Current Operator/Maintenance Manual
No

CONTROL STATION

Seat/Armrests
No visible damage or missing components

Glass
No visible damage or missing components

Cab Doors
No visible damage or missing components

Steering Controls
Rating:
Good

Hydraulic Controls
Rating:
Good

Drivetrain Controls
Rating:
Good

Dash Console
Rating:
Good

Engine Oil Pressure
The fault indicator shuts off after the engine oil pressure rises.

Warning Lights
Operational

Gauges
Operational

Rear View Camera
Camera operates as intended

Air Conditioner
Operational

Heater
Operational

Limited Function Check (Control Station)
The main components are in place and operational as noted.

Control Station
Cab Type, Enclosed Cab, Air Conditioner, Rear View Camera, Autoshift

Hour Meter /Odometer Usage Reading (Start)
8890 hrs

Hour Meter / Odometer
8891 hrs

ENGINE

A/C Compressor
Operational

Blow-by (Subjective Visual Observation)
No noticeable vapor or pressure

Starter
Operational

Exhaust System
No visible damage or missing components

Radiator
Rating:
Good

Oil Leaks
No dripping leaks

Fuel Leaks
No dripping leaks

Cooling System Leaks
No dripping leaks

Limited Function Check (Engine)
The engine started and ran.

Engine
2020 US EPA Label, Requires Diesel Exhaust Fluid

DRIVETRAIN

Transmission

Operational

Transfer Case / Drop Box
Rating:
Good

Front Drive Axle
Rating:
Good

Rear Drive Axle
Rating:
Good

Final Drives
Rating:
Good

Limited Function Check (Drivetrain)
The drivetrain was operational.

HYDRAULICS

Pumps (Hydraulics)
Rating:
Good

Valves
Rating:
Good

Hydraulic Tank
Rating:
Good

Hoses (Hydraulics)
Rating:
Good

Loader Lift Cylinders
Rating:
Good

Bucket Tilt Cylinders
Rating:
Good

Auxiliary Hydraulic Plumbing
Capped off, Not operationally checked

Steering Cylinders
Rating:
Good

Limited Function Check (Hydraulics)
The hydraulic system was operational.

CHASSIS

Lift Arm Condition
Rating:
Good

Chassis To Arm Pins
Rating:
Good

Tilt Linkage
Rating:
Good

Tilt Linkage Pins And Bushings
Rating:
Good

Bucket To Arm Pins
Rating:
Good

Limited Function Check (Chassis)
The main chassis components were operational in a limited check.

Articulating Center Pins
Rating:
Good

Brake Type
Hydraulic

Master Cylinder
Rating:
Good

Brake Lines/Hoses
Rating:
Good

Park Brake
Inoperable

Limited Function Check - Brakes
The service brakes were operational.

Frame Condition
Rating:
Good

Left Front Tire
Yokohama Radial RB31 29.5R25 56/32" Tread Depth
Rating:
Good

Left Rear Tire
Triangle TB516 29.5r25 11/32" Tread Depth
Rating:
Fair

Right Rear Tire
Triangle TB516 29.5r25 11/32" Tread Depth
Rating:
Fair

Right Front Tire
Yokohama Radial RB31 29.5R25 55/32" Tread Depth
Rating:
Good

Wheel Condition
No visible damage or missing components

SPECIALTY

Front Attachment
Auxiliary Hydraulics

CHECK SECTION

TIRE SIZE: 29.5R25

56/32
N/A
N/A

N/A

N/A

55/32
N/A
N/A



TIRE SIZE: 29.5R25



RECONDITIONING

Park Brake - Inop	$750
Paint - Damaged	$2,000
Right side body panel/cover - damaged	$3,000
Left front fender - damaged	$1,500
Left rear step - bent	$300
Right front hand rails - bent	$600
4 Exterior Lights - Inop	$1,200
Grille - damaged	$2,500
Left rear fender - damaged	$1,500

Right front fender - damaged	$1,500
Right rear fender - damaged	$1,500
Total	**$16,350**