2023 DOOSAN DL280-7

UNIT: DWGCWLDKHN1010165

Current Location: Swiderski Equipment Inc., Wausau, WI 54401, 715-573-8377





UNIT SPECS

Customer	PNC Equipment Finance

RECONDITIONING

Right side mirror - cracked	$150
Left front fender - damaged	$1,500
Right rear fender - damaged	$1,500
Engine compartment door stuck -	$350
Right fender - damaged, fender frame damage	$1,500
Left rear fender - damaged	$1,500
Right rear step near engine - damaged	$300
Total	$6,800

Tire Size: 20.5R25

33/32 N/A N/A

N/A

N/A

33/32 N/A N/A

Tire Size: 20.5R25

35/32 N/A N/A

N/A

N/A

35/32 N/A N/A


DL 280
DOOSAN


DL 280
DOOSAN


Hyundai Doosan Infracore Co. Ltd
489, Injung-Ro, Dong-gu,
Incheon, Korea
MODEL
제품명
PRODUCT IDENTIFICATION NUMBER
제품 식별 번호
>DWGCWLDKHN1010165<
MADE IN KOREA
950209-02977C


DL 280






PASS
DOOSAN
CONNECT


DOOSAN






DOOSAN


OOSAN
280


DOOR OPEN
SWITCH
EMERGENCY
STOP


DOOSAN






DL 280


DOOSAN


ENGINE
START
STOP


1
2
3
4
F
N
R


DOOSAN
F N R
1
2
3


DOOSAN
PN
1100 rpm
km/h
mph
20
30
10
40
50
25


DOOSAN
PN
1100 rpm
mph
km/h
DOOSAN


DOOSAN
PN
1100 rpm
mph
km/h
DOOSAN