2025 DEVELON DTL35-US31

UNIT: DHKCCLAATR0001109





UNIT SPECS

Customer	PNC Equipment Finance

LOCATION

R&M
25480 Alabama Highway 20
Mooresville, AL 35649

GENERAL APPEARANCE

Year
2025

Make
Develon

Model
DTL35-US31

Unit Number
CS-38496

Serial Number / VIN
DHKCCLAATR0001109

Serial
DHKCCLAATR0001109

Paint
Damage

Body Panels
Grille damaged

Cab/Canopy Overhead Structural Framework
No visible damage

Steps
No visible damage or missing components

Hand Rails
No visible damage or missing components

Exterior Lights
All lights operational

MODEL DESCRIPTION

Model Description
High Flow

SAFETY

Travel Alarm
Operational

Horn
Operational

Seat Belts
Operational

Current Safety Manual
Yes

Current Operator/Maintenance Manual
Yes

CONTROL STATION

Seat/Armrests
No visible damage or missing components

Glass
No visible damage or missing components

Cab Door
No visible damage or missing components

Steering Controls
Rating:
Good

Hydraulic Controls
Rating:
Good

Auxiliary Hydraulic Control
Rating:
Good

Drivetrain Controls
Rating:
Good

Dash Console
Rating:
Good

Warning Lights
Operational, Low coolant light stays on

Gauges
Operational

Rear View Camera
Camera operates as intended

Air Conditioner
Operational

Heater
Operational

Limited Function Check (Control Station)
The main components are in place and operational as noted.

Control Station
Enclosed Cab, Air Conditioner, Joystick Steering, Rear View Camera

Hour Meter /Odometer Usage Reading (Start)
591 hrs

Hour Meter / Odometer
591 hrs

ENGINE

A/C Compressor
Operational

Blow-by (Subjective Visual Observation)
Minor

Starter
Operational

Exhaust System
No visible damage or missing components

Radiator
Rating:
Good

Limited Function Check (Engine)
The engine started and ran.

Engine
2024 US EPA Label, Requires Diesel Exhaust Fluid

DRIVETRAIN

Drive Motors
Rating:
Good

Final Drives
Rating:
Good

Good

Limited Function Check (Drivetrain)
The drivetrain was operational.

HYDRAULICS

Pumps (Hydraulics)
Rating:
Good

Valves
Rating:
Good

Hydraulic Tank
Rating:
Good

Hoses (Hydraulics)
Rating:
Good

Auxiliary Hydraulic Plumbing
Not operationally checked

Loader Lift Cylinders
Rating:
Good

Bucket Tilt Cylinders
Rating:
Good

Limited Function Check (Hydraulics)
The hydraulic system was operational.

CHASSIS

Frame Condition
Rating:
Good

Belly Pans
Rating:
Good

Lift Arm Condition
Rating:
Good

Chassis To Arm Pins
Rating:
Good

Quick Coupler To Arms Pins
Rating:
Good

Limited Function Check (Chassis)
The main chassis components were operational in a limited check.

UNDERCARRIAGE

Undercarriage
18 in Track Belts

Roller Frames
Rating:
Good

Grouser Height Measurement
Left side: 19 mm, Right side: 20 mm

Track Belt Condition
No visible damage

Rubber Belt Drive Lugs
No visible damage

Track Tensioners
No visible damage

SPECIALTY

Quick Coupler
Not operationally checked, Cover bolts loose.

Front Attachment
Front Attachment Details, Electric Kit, Quick Coupler Type: Hydraulic Coupler

RECONDITIONING

Paint: Damage	$1,500
Body Panels: Grille damaged	$2,500
Quick Coupler: Not operationally checked, Cover bolts loose.	$250
Total	**$4,250**