

2023 DEVELON DX225-LC7

UNIT: DHKCEBDVEN0001198

Price: \$0.00 USD



GENERAL APPEARANCE

Year
2023

Make
DEVELON

Model
DX225-LC7

Unit Number
1008640

Serial
DHKCEBDVEN0001198

Pre-Operational Checks

Hydraulic oil is low, Confirm Fluids Checked: Engine Coolant. Confirm Fluids Checked: Engine(s) Oil. N/A: Transmission Fluid. Confirm Fluids Checked: Hydraulic Fluid. Confirm Fluids Checked: Fuel Level

Paint

Damage

Body Panels

No visible damage or missing components

Cab/Canopy Overhead Structural Framework

No visible damage

Steps

Tool box step damaged

Hand Rails

No visible damage or missing components

Serial Number / VIN

DHKCEBDVEN0001198

SAFETY

Travel Alarm

Operational

Horn

Operational

Seat Belts

Operational

Safety Lock Out/Stop

Operational

Swing Brake

Operational

Current Safety Manual

No

Current Operator/Maintenance Manual

No

CONTROL STATION

Seat/Armrests

No visible damage or missing components

Glass

No visible damage or missing components

Cab Door

No visible damage or missing components

Steering Controls

Rating:

Good

Hydraulic Controls

Rating:

Good

Drivetrain Controls

Rating:

Good

Dash Console

Rating:

Good

Engine Oil Pressure

The fault indicator shuts off after the engine oil pressure rises.

Warning Lights

Operational

Gauges

Operational

Rear View Camera

Camera operates as intended

Air Conditioner

Operational

Heater

Operational

Limited Function Check (Control Station)

The main components are in place and operational as noted. Not the machine's original key fob. Sometimes difficult to start. Key fob not included

Control Station

Cab Details:, Air Conditioner, Rear View Camera

Hour Meter / Odometer

2896 mi

Hour Meter /Odometer Usage Reading (Start)

2896 hrs

ENGINE

A/C Compressor

Not visible

Blow-by (Subjective Visual Observation)

No noticeable vapor or pressure

Starter

Operational

Exhaust System

No visible damage or missing components

Radiator

Rating:

Good

Oil Leaks

No dripping leaks

Fuel Leaks
No dripping leaks

Cooling System Leaks
No dripping leaks

Limited Function Check (Engine)
The engine started and ran.

Emission Status
Tier 4

Engine
No US EPA Label Present

DRIVETRAIN

Left Drive Motor
Rating:
Good

Right Drive Motor
Rating:
Good

Left Final Drive
Rating:
Good

Right Final Drive
Rating:
Good

Limited Function Check (Drivetrain)
The drivetrain was operational.

HYDRAULICS

Pumps (Hydraulics)
Rating:
Good

Valves
Rating:
Good

Hydraulic Tank
Low fluid level
Rating:
Good

Hoses (Hydraulics)
Rating:
Good

Auxiliary Hydraulic Plumbing
Operational, End of stick

Swing Motor

Rating:
Good

Hydraulic Center Swivel

Rating:
Good

Boom Lift Cylinder(s)

Rating:
Good

Stick Cylinder

Rating:
Good

Bucket Cylinder

Rating:
Good

Limited Function Check (Hydraulics)

The hydraulic system was operational.

CHASSIS

Boom/Stick Details

Standard Boom, 10 ft 0 in Stick

Boom Condition

Rating:
Good

Stick Condition

Rating:
Good

Swing Tower Pivot

Rating:
Good

Boom Base Pin And Bushings

Rating:
Good

Pin And Bushings Boom To Stick

Rating:
Good

Pins And Bushings Stick To Coupler

Heavy movement

Rating:
Fair

Bottom Covers

Rating:
Good

Limited Function Check (Chassis)

The main components were operational in a limited check.

UNDERCARRIAGE

Track Link Brand
Other Doosan Other Doosan

Left Roller Frame
Rating:
Good

Left Track Tensioner
Rating:
Good

Left Track Pads
32 in Wide Triple Grouser
Rating:
Good

Left Grouser Height
24 mm

Left Track Links
104 mm

Left Track Bushings
58 mm

Left Carrier Rollers
2 carrier rollers #1 142 mm #2 142 mm

Left Bottom Rollers
10 Bottom Rollers #1 160 mm #2 160 mm #3 160 mm #4 160 mm #5 160 mm #6 160 mm #7 160 mm #8 160 mm #9 160 mm
#10 160 mm

Left Idler
22 mm

Left Sprocket
Rating:
Good

Right Roller Frame
Rating:
Good

Right Track Tensioner
Rating:
Good

Right Track Pads
32 in Wide
Rating:
Good

Right Grouser Height
24 mm

Right Track Links
104 mm

Right Track Bushings

58 mm

Right Carrier Rollers
2 Carrier Rollers #1 142 mm #2 142 mm

Right Bottom Rollers
10 Bottom Rollers: #1 160 mm #2 160 mm #3 160 mm #4 160 mm #5 160 mm #6 160 mm #7 160 mm #8 160 mm #9 160 mm #10 160 mm

Right Idler
22 mm

Right Sprocket
Rating:
Good

SPECIALTY

Hydraulic Breaker
Rating:
Good

Quick Coupler
Not operationally checked

Front Attachment
Hydraulic Quick Coupler

LOGISTICS INFORMATION

Shipping Dimensions
35 ft Long x 11 ft 3 in Wide x 10 ft Tall

General Shipping Information
Yes: Does this Unit Run? Yes: If self propelled, does the unit travel? No: Is the unit taller than 12'? Yes: Is the unit wider than 8'6"? Yes: Inflated Tires - item can roll? No: Noticeable fluid leaks?

Road Related Shipping Info
Yes: Lights Operate? Yes: Brakes Operate?

RECONDITIONING

Pins And Bushings Stick To Coupler: Heavy movement	\$4,000
--	---------

Paint: Damage	\$2,500
Steps: Tool box step damaged	\$300
Check Engine Light On	\$5,500
Total	\$12,300

UNIT SPECS

Customer	Auxilior Capital	Year	2023
Make	DEVELON	Model	DX225-LC7
Unit Number	1008640		

INSPECTION LOCATION



Central Power Systems & Services
Midland, TX 79706
432-248-8344

CURRENT LOCATION



Central Power Systems & Services
Midland, TX 79706
432-248-8344

VERSION HISTORY ?

✓ 10/20/2026