

2021 DOOSAN DL250

Current Location: RTL Equipment, Big Lake, MN 55309, 763-337-2394

UNIT: DHKCWL BSSL5050343



UNIT SPECS

Customer PNC Equipment Finance

RECONDITIONING

Drivetrain Controls: Loose	\$400	Paint: Damage	\$2,000
Fenders: Left front damaged, Right front damaged	\$4,000	Left cab steps damaged, Right cab steps damaged	\$1,200
Exterior Lights: 2 Inoperable / damaged / missing	\$600		

Total \$8,200



































































