2023 DOOSAN DL250-7

UNIT: DHKCWLDSPP5050330

Price: $0.00 USD

View Asset


































DOOSAN




















ND DE
































GENERAL APPEARANCE

Year
2023

Make
Doosan

Model
DL250-7

Unit Number
DHKCWLDSPP5050330

Pre-Operational Checks

Confirm Fluids Checked: Engine Coolant. Confirm Fluids Checked: Engine(s) Oil. Confirm Fluids Checked: Transmission Fluid. Confirm Fluids Checked: Hydraulic Fluid. Confirm Fluids Checked: Fuel Level

Paint
Damage

Body Panels
Grille damaged

Fenders
Left front damaged, Right front damaged

Steps
Left cab steps damaged, Right cab steps bent

Hand Rails
No visible damage or missing components

Exterior Lights
2 Inoperable / damaged / missing

Cab/Canopy Overhead Structural Framework
Bent metal

Serial Number / VIN
DHKCWLDSPP5050330

Serial Number
DHKCWLDSPP5050330

SAFETY

Travel Alarm
Operational

Horn
Operational

Seat Belts
Operational

CONTROL STATION

Seat/Armrests
No visible damage or missing components

Glass
No visible damage or missing components

Cab Doors
No visible damage or missing components

Steering Controls
Rating:
Good

Hydraulic Controls
Rating:
Good

Drivetrain Controls
Rating:
Good

Dash Console
Rating:
Good

Warning Lights
Operational, Check engine light stays on

Gauges
Operational

Rear View Camera
Camera operates as intended

Air Conditioner
Operational

Heater
Operational

Limited Function Check (Control Station)
The main components are in place and operational as noted.

Control Station
Cab Type, Enclosed Cab, Air Conditioner, Rear View Camera, Air Ride Seat, Ride Control, Autoshift, Traction Control

Hour Meter /Odometer Usage Reading (Start)
2600 hrs

Hour Meter / Odometer
2601 hrs

ENGINE

A/C Compressor
Operational

Blow-by (Subjective Visual Observation)
No noticeable vapor or pressure

Starter
Operational

Exhaust System
No visible damage or missing components

Radiator
Rating:
Good

Limited Function Check (Engine)
The engine started and ran.

Engine
2023 US EPA Label, Requires Diesel Exhaust Fluid

DRIVETRAIN

Transmission
Operational
Rating:
Good

Transfer Case / Drop Box
Operational
Rating:
Good

Front Drive Axle
Rating:
Good

Rear Drive Axle
Rating:
Good

Final Drives
Rating:
Good

Limited Function Check (Drivetrain)
The drivetrain was operational.

HYDRAULICS

Pumps (Hydraulics)
Rating:
Good

Valves
Rating:
Good

Hydraulic Tank
Rating:
Good

Hoses (Hydraulics)
Rating:
Good

Loader Lift Cylinders
Rating:
Good

Bucket Tilt Cylinders
Rating:
Good

Steering Cylinders
Rating:
Good

Limited Function Check (Hydraulics)
The hydraulic system was operational.

CHASSIS

Lift Arm Condition
Rating:
Good

Chassis To Arm Pins
Rating:
Good

Tilt Linkage
Rating:
Good

Tilt Linkage Pins And Bushings
Rating:
Good

Quick Coupler To Arms Pins
Rating:
Good

Limited Function Check (Chassis)
The main chassis components were operational in a limited check.

Articulating Center Pins
Rating:
Good

Brake Type
Hydraulic

Master Cylinder
Rating:
Good

Brake Lines/Hoses
Rating:
Good

Park Brake
Stopped from a slow roll
Rating:
Good

Limited Function Check - Brakes
The brake system functioned, stopping and holding the machine.

Frame Condition
Rating:
Good

Left Front Tire
Triangle TB516 20.5R25 23/32" Tread Depth
Rating:
Fair

Left Rear Tire
Triangle TB516 20.5R25 22/32" Tread Depth
Rating:
Fair

Right Rear Tire
Triangle TB516 20.5R25 18/32" Tread Depth
Rating:
Fair

Right Front Tire
Triangle TB516 20.5R25 23/32" Tread Depth
Rating:
Fair

Wheel Condition
No visible damage or missing components

SPECIALTY

Front Attachment
Hydraulic Coupler, 3.5 cyd 107 in Bucket

Loader Bucket Condition
Rating:
Good

Loader Bucket Cutting Edge
No visible damage or missing components
Rating:
Good

Loader Quick Coupler
Rockland Coupler, Operational
Rating:
Good

TIRE SIZE: 20.5R25

23/32			23/32
N/A	N/A	N/A	N/A
N/A			N/A

TIRE SIZE: 20.5R25

22/32			18/32
	N/A	N/A	
N/A N/A			N/A N/A

CHECK SECTION

RECONDITIONING

Check engine light on	$2,500
Paint - Damaged	$2,000
Grille - damaged	$2,500
Both front fenders - damaged	$3,000
Left cab steps - damaged	$600
2 Exterior Lights - Inop	$600
Cab/Canopy Overhead Structural Framework Metal - Bent	$500
Right cab steps - bent	$600

Total	**$12,300**

UNIT SPECS

Customer	Wells Fargo (IMS)

INSPECTION LOCATION

Wells Fargo (IMS)
Orlando, FL 32810
555-555-5555

CURRENT LOCATION

Wells Fargo (IMS)
Orlando, FL 32810
555-555-5555

VERSION HISTORY

✔ 09/25/2026