# 2018 DOOSAN DX350LC

UNIT: 1020269

**Current Location:** R.B. Everett & Company, Pasadena, TX 77507, 281-991-8161





## UNIT SPECS

| | |
|---|---|
| **Customer** | PNC Equipment Finance |
| **Year** | 2018 |
| **Make** | Doosan |
| **Model** | DX350LC |
| **Unit Number** | 160595 |

## RECONDITIONING

| | | | |
|---|---|---|---|
| **Mirrors: One is damaged** | $150 | **Paint: Damage** | $2,500 |
| **Body Panels: Right rear door damaged** | $3,000 | **Quick Coupler: Operational, Cylinder is leaking** | $750 |

**Total** $6,400


DOOSAN


DOOSAN
DX350LC


DOOSAN
Doosan Infracore Co., Ltd.
489, Injung-Ro, Dong-gu,
Incheon, Korea
MODEL
제품명
DX350LC-5
PRODUCT IDENTIFICATION NUMBER
제품 식별 번호
>DWGCECEBEJ1020269<
MADE IN KOREA
950209-02977B


DOOSAN


DX35








DOOSAN


DOOSAN


DOOSAN


DOOSAN
DX350LC


DOOSAN


DOOSAN








DOOSAN


DOOSAN


DOOSAN




DOOSAN


DOOSAN



DOOSAN



DOOSAN






DOOSAN




DOOSAN


DOOSAN


DOOSAN