2023 DEVELON DX420LC-7

UNIT: DWGCECGUEP1010025

Price: $0.00 USD

View Asset















GENERAL APPEARANCE

Year
2023

Make
Develon

Model
DX420LC-7

Unit Number
DWGCECGUEP1010025

Serial
DWGCECGUEP1010025

CE Mark
No CE mark found

Pre-Operational Checks

Confirm Fluids Checked: Engine Coolant. Confirm Fluids Checked: Engine(s) Oil. Confirm Fluids Checked: Transmission Fluid. Confirm Fluids Checked: Hydraulic Fluid. Confirm Fluids Checked: Fuel Level

Paint
Damage

Body Panels
Right rear door damaged

Cab/Canopy Overhead Structural Framework
No visible damage

Steps
No visible damage or missing components

Hand Rails
No visible damage or missing components

Exterior Lights
All lights operational

Serial Number / VIN
DWGCECGUEP1010025

SAFETY

Travel Alarm
Operational

Horn
Operational

Seat Belts
Operational

Safety Lock Out/Stop
Operational

Swing Brake
Operational

Current Safety Manual
No

Current Operator/Maintenance Manual
No

CONTROL STATION

Seat/Armrests
No visible damage or missing components

Glass
No visible damage or missing components

Cab Door
No visible damage or missing components

Steering Controls

Rating:
Good

Hydraulic Controls
Rating:
Good

Drivetrain Controls
Rating:
Good

Dash Console
Rating:
Good

Engine Oil Pressure
The fault indicator shuts off after the engine oil pressure rises.

Warning Lights
Operational

Gauges
Operational

Rear View Camera
Camera operates as intended

Air Conditioner
Operational

Heater
Not operationally checked

Limited Function Check (Control Station)
The main components are in place and operational as noted.

Control Station
Cab Details:, Air Conditioner, Control Pattern Changer, Rear View Camera

Hour Meter / Odometer
2461 mi

Hour Meter /Odometer Usage Reading (Start)
2460 hrs

ENGINE

A/C Compressor
Operational

Blow-by (Subjective Visual Observation)
No noticeable vapor or pressure

Starter
Operational

Exhaust System
No visible damage or missing components

Radiator

Rating:
Good

Oil Leaks
No dripping leaks

Fuel Leaks
No dripping leaks

Cooling System Leaks
No dripping leaks

Limited Function Check (Engine)
The engine started and ran.

Engine
2022 US EPA Label, CARB Compliant, Requires Diesel Exhaust Fluid

DRIVETRAIN

Left Drive Motor
Rating:
Good

Right Drive Motor
Rating:
Good

Left Final Drive
Rating:
Good

Right Final Drive
Rating:
Good

Limited Function Check (Drivetrain)
The drivetrain was operational.

HYDRAULICS

Pumps (Hydraulics)
Rating:
Good

Valves
Rating:
Good

Hydraulic Tank
Rating:
Good

Hydraulic Control Pattern Changer
Rating:
Good

Hoses (Hydraulics)
Rating:

Good

Auxiliary Hydraulic Plumbing
Not operationally checked

Swing Motor
Rating:
Good

Hydraulic Center Swivel
Rating:
Good

Boom Lift Cylinder(s)
Rating:
Good

Stick Cylinder
Rating:
Good

Bucket Cylinder
Rating:
Good

Limited Function Check (Hydraulics)
The hydraulic system was operational.

CHASSIS

Boom/Stick Details
Standard Boom, 10 ft 3 in Stick

Boom Condition
Rating:
Good

Stick Condition
Rating:
Good

Boom Base Pin And Bushings
Rating:
Good

Pin And Bushings Boom To Stick
Rating:
Good

Pin And Bushings Stick To Bucket
Heavy movement
Rating:
Good

Turntable Bearing
Rating:
Good

Bottom Covers
1 Damaged

Limited Function Check (Chassis)
The main components were operational in a limited check.

UNDERCARRIAGE

Track Link Brand
Other Doosan Other Doosan

Left Roller Frame
Rating:
Good

Left Track Tensioner
Rating:
Good

Left Track Pads
31.5 in Wide Triple Grouser

Left Grouser Height
35 mm

Left Track Links
128 mm

Left Track Bushings
68 mm

Left Carrier Rollers
2 carrier rollers #1 177 mm #2 177 mm #3 N/A mm #4 N/A mm

Left Bottom Rollers
9 Bottom Rollers #1 CM mm #2 CM mm #3 Guard mm #4 CM mm #5 195 mm #6 CM mm #7 Guard mm #8 CM mm #9 193 mm #10 N/A mm

Left Idler
CM mm

Left Sprocket
Rating:
Good

Right Roller Frame
Rating:
Good

Right Track Tensioner
Rating:
Good

Right Track Pads
31.5 in Wide Triple Grouser
Rating:
Good

Right Grouser Height
35 mm

Right Track Links

128 mm

Right Track Bushings
68 mm

Right Carrier Rollers
2 Carrier Rollers #1 178 mm #2 177 mm #3 N/A mm #4 N/A mm

Right Bottom Rollers
9 Bottom Rollers: #1 CM mm #2 CM mm #3 Guard mm #4 CM mm #5 196 mm #6 CM mm #7 Guard mm #8 CM mm #9 194 mm #10 N/A mm

Right Idler
CM mm

Right Sprocket
Rating:
Good

SPECIALTY

Excavator Bucket Condition
Rating:
Good

Bucket Cutting Edge/Shanks/Teeth
Rating:
Good

Front Attachment
66 in Digging Bucket

RECONDITIONING

Pin And Bushings Stick To Bucket: Heavy movement	$4,500
Bottom Covers: 1 Damaged	$500
Paint: Damaged	$3,000

Right rear door: damaged	$3,000
Total	**$11,000**

UNIT SPECS

Customer	Wells Fargo (IMS)	**Year**	2023
Make	Develon	**Model**	DX420LC-7
Unit Number	DWGCECGUEP1010025		

INSPECTION LOCATION

Wells Fargo (IMS)
Doral, FL 33166
555-555-5555

CURRENT LOCATION

Wells Fargo (IMS)
Doral, FL 33166
555-555-5555

VERSION HISTORY

✔ 07/15/2026