

2021 DOOSAN DX225LC-5

UNIT: DHKCEBBUEM0003378

Current Location: ACT Construction Equipment, Winston Salem, NC 27107, 919-717-9403



UNIT SPECS

Customer	PNC Equipment Finance
Year	2021
Make	Doosan
Model	DX225LC-5
Unit Number	193724

RECONDITIONING

Rear View Camera: Display inoperable, 1&2 have image; camera 3 has a blue screen	\$1,000	Exhaust System: Exhaust pipe damaged	\$650
Paint: Damage	\$1,000	Body Panels: Left rear door damaged, Right rear door damaged,	\$6,000
Hand Rails: Tool box step hand rail damaged	\$600	Exterior Lights: 1 Inoperable / damaged / missing Right rear of boom missing	\$200
Left Side Cover damaged, Right side cover damaged	\$5,000		
Total			\$14,450



























