

2019 DOOSAN DL250-5

Current Location: RB EVERETT, HALTOM CITY, TX 76117, 281-991-8161

UNIT: DHKCWLBSAK5050023



UNIT SPECS

Customer PNC Equipment Finance

RECONDITIONING

Paint: Damage	\$2,500	Body Panels: Left rear door damaged	\$2,500
Fenders: Right front damaged, Right rear damaged	\$4,500	Left cab steps bent, Right cab steps bent	\$1,200
Horn: Inoperable	\$200	Loader Bucket Cutting Edge: Edge worn	\$550
Total			\$11,450



































EMISSION CONTROL INFORMATION
This Engine complies with U.S. EPA and California
regulation for 2010 nonroad diesel engines.
Emission Control System
EGR, DOC, SCR, DFI, TC, CAC, DEF, DQ
Power Category : 130 < kW < 560
US Engine Family : KDIC105.8LEA
Engine Code : DL06-LEL06
Manufactured by Doosan Infracore Co., Ltd.
Date Of Manufacture : 01 / 01
Ultra Low Sulfur Fuel













































