

2023 DOOSAN DLL220-7

UNIT: DHKCWLDVKN5050303

Current Location: Best Line Equipment, Shippensburg, PA 17257, 717-729-0631



UNIT SPECS

Customer PNC Equipment Finance

RECONDITIONING

Transmission: leak	\$5,500	Rear access door latch: not operational and door would not open	\$400
Hoses (Hydraulics): Damaged hoses going to the quick coupler	\$500	Safety Lock Out/Stop: Parking brake switch is damaged	\$500
Total			\$6,900

Tire Size: 20.5R25

33_{/32} N/A
N/A

N/A

N/A

32_{/32} N/A
N/A

Tire Size: 20.5R25

33_{/32} N/A
N/A

N/A

N/A

33_{/32} N/A
N/A



Hyundai Doosan Infracore Co. Ltd
489, Injung-Ro, Dong-gu,
Incheon, Korea

MODEL

DL220-7

제품명

PRODUCT IDENTIFICATION NUMBER

제품 식별 번호

>DHKCWLDVKN5050303<

MADE IN KOREA

950209-02977C





