



UNIT SPECS

Customer PNC Equipment Finance

RECONDITIONING

Check engine light stays on	\$2,500	Hood: damaged	\$4,500
Cab/Canopy Overhead Structural Framework: Cracked Plastic	\$450	All 6 Exterior Lights: Inoperable	\$1,800
Left engine door: missing	\$1,500	Right cab door: damaged	\$4,500
Grille: damaged	\$2,000	Exhaust stack: damaged	\$550
Paint: damaged	\$2,000		

Total

\$19,800

























