




UNIT SPECS

Customer

Auxilior Capital

RECONDITIONING

Rear View Camera: inoperable	\$1,000	Paint: Damaged	\$3,000
Right side cover: damaged	\$2,500	Left track frame steps: bent	\$600
Tool box step hand rail: bent	\$800	Right track frame steps: bent	\$600
Tool box step: bent	\$300		
Total			\$8,800



























































DOOSAN EMISSION CONTROL INFORMATION

THIS ENGINE COMPLIES WITH U.S. EPA REGULATIONS FOR 2022 NONROAD DIESEL
ENGINES AND CALIFORNIA REGULATIONS FOR 2022 OFF-ROAD DIESEL ENGINES.

EMISSION CONTROL SYSTEM

: EGR, DOC, SCR, DFI, TC, CAC, ECM, DOS
POWER CATEGORY : 130 $\pm$ kW $\pm$ 500
US ENGINE FAMILY : NOICL07.0LEA
ENGINE CODE : DLO8-LEE00

MANUFACTURED BY HYUNDAI DOOSAN INFRACORE CO., LTD.
DATE OF MANUFACTURE : 05 / 2022
ULTRA LOW SULFUR FUEL ONLY

DOOSAN Doosan Infracore

CAUTION-OIL SPECIFICATION

API CJ-4, ACEA E9
LOW ASH OIL IS REQUIRED.

WARNING

: Cancer and Reproductive Harm -
www.P66Warnings.ca.gov

DOOSAN

Model : DLO8P
Serial No : 024641
Option : DLO8-LEE00









