

2023 DOOSAN DL280-7

Current Location: Dynamic Equipment, Orlando, FL 32810, 407-273-7383

UNIT: DWGCWLDKVP1010312



UNIT SPECS

Customer

Auxilior Capital

RECONDITIONING

Seat/Armrests: Operator seat cover torn \$450

Paint: Damage \$2,500

Left cab steps damaged, Right cab steps damaged \$1,200

Total

\$4,150










































































PN =

29 1 1.7 Hour



PN =

29 1 1.3 Hour



