2023 DEVELON DX140LCR-7

UNIT: DHKCEBDUAN0001110

Current Location: R.B. Everett & Co., Pasadena, TX 77507, 281-991-8161





UNIT SPECS

Customer	PNC Equipment Finance
Year	2023
Make	Develon
Model	DX140LCR-7
Unit Number	235840

RECONDITIONING

Mirrors: Mirror is missing on the right side	$150
Body Panels: Right front door and panel is damaged.	$4,500
Steps: Tool box step damaged	$300
Bucket Cutting Edge/Shanks/Teeth: Teeth worn	$750
Paint: Damage	$2,500
Panel under front glass is damaged	$2,000
Hand Rails: Cab entry hand rail damaged, Tool box step hand rail damaged	$1,200


Total $11,400


DOOSAN
DOOSAN
BOMAG


DOOSAN
DOOSAN


Hyundai Doosan Infracore Co. Ltd
48º, Injung-Ro, Dong-gu,
Incheon, Korea
MODEL
제품명
PRODUCT IDENTIFICATION NUMBER
제품 식별 번호
MADE IN KOREA
960209-02977C


DOOSAN
BOMAG


Everett
DX140LCR


DL420
DX62R


BOMAG
BOMAG
Everett
DOOSAN
CONNECT
DX 140 LCR




BOMAG
DX 140 LGR


Everett
DOOSAN
DX 140 LGR


DOOSAN


DOOS
Everett
DX 140 LCR


DOOSAN


DX 140 LCR


Everett
DX 140 LCR


SOLD SERVICED RENTED BY
Everett
DX 140 LCR


OSAN
Everett
DX 140 LCH


DOOSAN


DOOSAN
DOOSAN
DX 140 LCR
DEVELON


DOOSAN
DOOSAN
CONNECT
DX 140 LCR


SOLD SERVICED RENTED BY
R.B.
Everett
& Co.
PASADENA, TEXAS
HALTOM CITY, TEXAS
DOOSAN
CONNECT
DX 140 LCR





