

2020 DOOSAN DX140LCR-5

Current Location: RTL EQUIPMENT, Brainerd, MN 56401, 218-829-2800

UNIT: DHKCEBBSVJ0002204



UNIT SPECS

Customer	PNC Equipment Finance
Year	2020
Make	DOOSAN
Model	DX140LCR-5
Unit Number	170625

RECONDITIONING

Seat/Armrests: Operator seat cushion damaged	\$450	Mirrors: Mirror is cracked and damaged	\$150
Paint Damage	\$2,500		
Total			\$3,100





Doosan Infracore Co., Ltd.
489, Injung-Ro, Dong-gu,
Incheon, Korea

MODEL

제품명

DX140LCR-5

PRODUCT IDENTIFICATION NUMBER

제품 식별 번호

>DHKCEBBSVJ0002204<

MADE IN KOREA

950209-02977B























































































































MODEL [PLMT-DS DX140 RR 12HE RCT NO. CDR]
CARRIER MODEL [DX140]
[]
SERIAL NO. [1221]
[]
[]
MI NO. [PL140C4T] MADE IN [USA]
DOOSAN
West Fargo, ND 58078 USA
www.doosan.com

 **WARNING**