

2022 DOOSAN DX180LC-5

Current Location: PNC Equipment Finance, Richland, MS 39218, 267-960-4018

UNIT: DHKCEBBTCN0001737



UNIT SPECS

Customer	PNC Equipment Finance
Year	2022
Make	Doosan
Model	DX180LC-5

RECONDITIONING

Bottom Covers: 4 Damaged	\$2,000	Paint: Damaged	\$3,000
Left rear door: damaged	\$2,500	Exterior Lights: 2 Inoperable	\$600
Steps To Engine Bay: Damaged	\$3,500	Pin and Bushings Boom to Stick: Slack	\$4,000
Pins and Bushings Stick to Coupler: Slack	\$4,500		
Total		\$20,100	











































































































