

2025 DEVELON DX55R-7

UNIT: DHKCEADWTR0001830

Price: \$0.00 USD



GENERAL APPEARANCE

Year
2025

Make
DEVELON

Model
DX55R-7

Unit Number
C36279

Serial
DHKCEADWTR0001830

Pre-Operational Checks

Confirm Fluids Checked: Engine Coolant. Confirm Fluids Checked: Engine(s) Oil. Confirm Fluids Checked: Transmission Fluid. Confirm Fluids Checked: Hydraulic Fluid. Confirm Fluids Checked: Fuel Level

Paint

No visible damage

Body Panels

No visible damage or missing components

Cab/Canopy Overhead Structural Framework

No visible damage

Steps

No visible damage or missing components

Hand Rails

No visible damage or missing components

Exterior Lights

All lights operational

Serial Number / VIN

DHKCEADWTR0001830

SAFETY

Travel Alarm

Operational

Horn

Operational

Seat Belts

Operational

Safety Lock Out/Stop

Operational

CONTROL STATION

Seat/Armrests

No visible damage or missing components

Glass

Cab door shattered

Cab Door

No visible damage or missing components

Steering Controls

Rating:

Good

Hydraulic Controls

Rating:

Good

Drivetrain Controls

Rating:

Good

Dash Console

Rating:

Good

Warning Lights
Operational

Gauges
Operational

Rear View Camera
Camera operates as intended

Air Conditioner
The ambient temperature is too cold to check

Heater
Operational

Limited Function Check (Control Station)
The main components are in place and operational as noted.

Control Station
Cab Details:, Cab Type Enclosed Cab, Air Conditioner, Control Pattern Changer, Rear View Camera

Hour Meter / Odometer
393 hrs

Hour Meter /Odometer Usage Reading (Start)
393.6 hrs

ENGINE

A/C Compressor
In place; ambient temperature too cold to check operation

Starter
Operational

Exhaust System
No visible damage or missing components

Radiator
Rating:
Good

Oil Leaks
No dripping leaks

Limited Function Check (Engine)
The engine started and ran.

Engine
2023 US EPA Label

DRIVETRAIN

Left Drive Motor
Rating:
Good

Right Drive Motor

Rating:

Good

Left Final Drive

Rating:

Good

Right Final Drive

Rating:

Good

Limited Function Check (Drivetrain)

The drivetrain was operational.

HYDRAULICS

Pumps (Hydraulics)

Rating:

Good

Valves

Rating:

Good

Hydraulic Tank

Rating:

Good

Hydraulic Control Pattern Changer

Rating:

Good

Hoses (Hydraulics)

Rating:

Good

Auxiliary Hydraulic Plumbing

Operational, End of stick

Swing Motor

Covered

Rating:

Good

Hydraulic Center Swivel

Covered

Rating:

Good

Boom Swing Cylinders

Rating:

Good

Boom Lift Cylinder(s)

Rating:

Good

Stick Cylinder

Rating:

Good

Bucket Cylinder

Rating:

Good

Thumb Cylinder

Rating:

Good

Blade Lift Cylinder

Rating:

Good

Limited Function Check (Hydraulics)

The hydraulic system was operational.

CHASSIS

Boom/Stick Details

Swing Boom, 5 ft 3 in Stick, Auxiliary Hydraulic Plumbing

Boom Condition

Rating:

Good

Stick Condition

Rating:

Good

Swing Tower Pivot

Rating:

Good

Boom Base Pin And Bushings

Rating:

Good

Pin And Bushings Boom To Stick

Rating:

Good

Pins And Bushings Stick To Coupler

Rating:

Good

Turntable Bearing

Rating:

Good

Bottom Covers

Rating:

Good

Limited Function Check (Chassis)

The main components were operational in a limited check.

UNDERCARRIAGE

Track Link Brand
Other Develon Other Develon

Left Track Pads
15.75 in Wide
Rating:
Good

Right Track Pads
15.75 in Wide
Rating:
Good

RUBBER TRACK UNDERCARRIAGE

Roller Frames
Rating:
Good

Track Pads
Rating:
Good

Grouser Height Measurement
Left side: 20 mm, Right side: 18 mm

Track Belt Condition
No visible damage

Track Tensioners
Operational

SPECIALTY

Thumb
Hydraulic thumb
Rating:
Good

Excavator Bucket Condition
Rating:
Good

Bucket Cutting Edge/Shanks/Teeth
No visible damage or missing components
Rating:
Good

Quick Coupler
Operational
Rating:
Good

Blade Condition
Rating:
Good

Front Attachment
Manual Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb

RECONDITIONING

Glass: Cab door shattered	\$1,500
Paint Damage	\$1,500
Total	\$3,000

UNIT SPECS

Customer	Auxilior Capital	Year	2025
Make	DEVELON	Model	DX55R-7
Unit Number	C36279		

INSPECTION LOCATION

 Cascade Trader
Chehalis, WA 98532
360-748-1182

CURRENT LOCATION

 Cascade Trader
Chehalis, WA 98532
360-748-1182

VERSION HISTORY ?

✓ 10/12/2026