

2024 DEVELON DX27Z-7

UNIT: DHKCEEAXLR0001619

Price: \$0.00 USD



GENERAL APPEARANCE

Year
2024

Make
DEVELON

Model
DX27Z-7

Unit Number
C34924

Serial
DHKCEEAXLR0001619

Paint
Damage, Scratched paint

Body Panels
Left Side Cover damaged

Cab/Canopy Overhead Structural Framework
No visible damage

Steps
No visible damage or missing components

Hand Rails
No visible damage or missing components

Exterior Lights
All lights operational

Serial Number / VIN
DHKCEEAXLR0001619

SAFETY

Travel Alarm
Operational

Horn
Operational

Seat Belts
Operational

CONTROL STATION

Seat/Armrests
No visible damage or missing components

Steering Controls
Rating:
Good

Hydraulic Controls
Rating:
Good

Drivetrain Controls
Rating:
Good

Dash Console
Rating:
Good

Warning Lights
Operational

Gauges
Operational

Limited Function Check (Control Station)
The main components are in place and operational as noted.

Control Station
Cab Details:, Cab Type Open Operator Station, Control Pattern Changer

Hour Meter / Odometer
0 hrs, Meter inoperable

Hour Meter /Odometer Usage Reading (Start)
0 hrs

ENGINE

Starter
Operational

Exhaust System
No visible damage or missing components

Radiator
Rating:
Good

Oil Leaks
No dripping leaks

Limited Function Check (Engine)
The engine started and ran.

Engine
2023 US EPA Label

DRIVETRAIN

Left Drive Motor
Rating:
Very Good

Right Drive Motor
Rating:
Good

Left Final Drive
Rating:
Good

Right Final Drive
Rating:
Good

Limited Function Check (Drivetrain)
The drivetrain was operational.

HYDRAULICS

Pumps (Hydraulics)
Rating:
Good

Valves
Rating:

Good

Hydraulic Tank

Rating:

Good

Hydraulic Control Pattern Changer

Rating:

Good

Hoses (Hydraulics)

Rating:

Good

Auxiliary Hydraulic Plumbing

Operational, End of stick

Swing Motor

Rating:

Good

Boom Swing Cylinders

Rating:

Good

Boom Lift Cylinder(s)

Rating:

Good

Stick Cylinder

Rating:

Good

Bucket Cylinder

Rating:

Good

Thumb Cylinder

Rating:

Good

Blade Lift Cylinder

Rating:

Good

Limited Function Check (Hydraulics)

The hydraulic system was operational.

CHASSIS

Boom/Stick Details

Swing Boom, 4 ft 4 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade

Boom Condition

Rating:

Good

Stick Condition

Rating:

Good

Swing Tower Pivot

Rating:

Good

Boom Base Pin And Bushings

Rating:

Good

Pin And Bushings Boom To Stick

Rating:

Good

Pins And Bushings Stick To Coupler

Rating:

Good

Turntable Bearing

Rating:

Good

Bottom Covers

Rating:

Good

Limited Function Check (Chassis)

The main components were operational in a limited check.

RUBBER TRACK UNDERCARRIAGE

Roller Frames

Rating:

Good

Grouser Height Measurement

Left side: 22 mm, Right side: 22 mm

Track Belt Condition

No visible damage

Rubber Belt Drive Lugs

No visible damage

Track Tensioners

Operational

SPECIALTY

Thumb

Hydraulic thumb

Rating:

Good

Excavator Bucket Condition

Rating:

Good

Bucket Cutting Edge/Shanks/Teeth

Rating:

Good

Quick Coupler
Not operationally checked

Blade Condition
Rating:
Good

Front Attachment
Manual Quick Coupler, 24 in Digging Bucket, Hydraulic Thumb

RECONDITIONING

Hour Meter / Odometer: 0 hrs, Meter inoperable	\$350
Damage, Scratched paint	\$1,500
Body Panels: Left Side Cover damaged	\$2,000
Total	\$3,850

UNIT SPECS

Customer	Auxilior Capital	Year	2024
Make	DEVELON	Model	DX27Z-7
Unit Number	C34924		

INSPECTION LOCATION



R & M Equipment

Mt Pleasant, TN 38474

800-700-0990

CURRENT LOCATION



R & M Equipment

Mt Pleasant, TN 38474

800-700-0990

VERSION HISTORY

✓ 10/23/2026