

Detailed Equipment Information

2022 DOOSAN DX225 LC / HEX

- Find it in Yard
 - General Appearance
 - Control Station
- Engine
 - Drivetrain
 - Hydraulics
- Chassis
 - Undercarriage
 - Specialty

FIND IT IN YARD

ASSIGNED LANE AND SPOT	Located in Lane 8 Spot 25
------------------------	---------------------------

Print

Download All Photos

Back To Top

GENERAL APPEARANCE

SERIAL NUMBER / VIN	DHKCEBBUAM0003554	
SELLER REFERENCE NUMBER	Seller Reference or Fleet Number:	
TIRES/ UNDERCARRIAGE	Percentage Rating:	
HOURLY METER / ODOMETER	3537.5 hrs	
CONDITION	Overall Condition for Age:, Fair	
FEATURES	Located in Lane 8 Spot 25, Air Conditioner, Cab Screens, Rear View Camera, 2021 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 7 in Stick, Auxiliary Hydraulic Plumbing, 31.5 in Triple Grouser Track Shoes, 48 in Digging Bucket, Hydraulic Thumb	

Back To Top





Photo 3



Photo 4



Photo 5

CONTROL STATION

CONTROL STATION

Cab Details:, Air Conditioner, Cab Screens,
Rear View Camera

LIMITED FUNCTION CHECK

The main components are in place and
operational as noted.

[Back To Top](#)



1 of 7



Photo 1



Photo 2



Photo 3

ENGINE

ENGINE

2021 US EPA Label, Requires Diesel Exhaust
Fluid

LIMITED FUNCTION CHECK

The engine started and ran.

[Back To Top](#)



1 of 5



Photo 1



Photo 2



Photo 3

DRIVETRAIN

[Back To Top](#)

LIMITED FUNCTION CHECK

The drivetrain was operational.



1 of 4



Photo 1

Photo 2

Photo 3

HYDRAULICS

LIMITED FUNCTION CHECK

The hydraulic system was operational.

[Back To Top](#)



1 of 6



Photo 1

Photo 2

Photo 3

CHASSIS

BOOM/STICK DETAILS

Standard Boom, 9 ft 7 in Stick, Auxiliary
Hydraulic Plumbing

[Back To Top](#)

LIMITED FUNCTION CHECK

The main components were operational in a
limited check.





Photo 2



Photo 3



Photo 4

UNDERCARRIAGE

UNDERCARRIAGE

31.5 in Triple Grouser Track Shoes

[Back To Top](#)



Photo 5



Photo 6



Photo 7

SPECIALTY

FRONT ATTACHMENT

48 in Digging Bucket, Hydraulic Thumb

[Back To Top](#)

DISCLAIMER

General

The Detailed Equipment Information is limited in scope, and Ritchie Bros. Auctioneers has not inspected any aspects or components of the equipment other than those expressly set forth herein. Unless expressly stated, we make no representations or warranties, express or implied, concerning the equipment or its components, including without limitation any representations or warranties concerning functionality, conformity or compliance with any safety standard or requirement of any applicable authority or regulatory body, fitness for any particular purpose, or merchantability. You are strongly advised to perform your own detailed inspection of the equipment prior to bidding.

Functions

Equipment is not tested under load. We make no representation or warranty that equipment is operating in accordance with manufacturers' specifications. No inspection has been performed with respect to any functionality aspect other than those expressly included herein. Only select photos have been provided for individual undercarriage components, and may not be indicative of the condition of the entire undercarriage as a whole.

Dimensions

Measurements are given as an estimate only. Actual loaded dimensions may vary based on truck/trailer height and the loaded machine configuration/position. It is the buyer's responsibility to measure all loads before leaving our auction site to ensure the load is safe for transport. All measurements should be verified by the buyer. DO NOT rely on these measurements for transportation purposes