

2018 DOOSAN DX225LC-5

Current Location: RGW Equipment, Livermore, CA 94550, 925-606-2463

UNIT: DHKCEBBULJ0002160



UNIT SPECS

Customer	PNC Equipment Finance
Year	2018
Make	Doosan
Model	DX225LC-5
Unit Number	185491

RECONDITIONING

Display inoperable	\$1,500	Paint: Damage	\$2,500
Body Panels: Left rear door damaged	\$3,000		
Total			\$7,000





Doosan Infracore Co., Ltd.
489, Injung-Ro, Dong-gu,
Incheon, Korea

MODEL
제품명

DX225LC-5

PRODUCT IDENTIFICATION NUMBER
제품 식별 번호

>0HKCEBBULJ0002160<

MADE IN KOREA

950209-02977B



















