




2024 DEVELON DX225LC-7 US20

UNIT: DHKCEBDPLR0002159











UNIT SPECS

Customer	PNC Equipment Finance	Year	2024
Make	DEVELON	Model	DX225LC-7 US20
Unit Number	226720		

LOCATION

DYNAMICC EQUIPMENT
768 Murray Rd
Dothan, AL 19044

GENERAL APPEARANCE

Year
2024

Make
DEVELON

Model
DX225LC-7 US20

Unit Number
226720

Serial
DHKCEBDPLR0002159

Pre-Operational Checks
Confirm Fluids Checked: Engine Coolant. Confirm Fluids Checked: Engine(s) Oil. Confirm Fluids Checked: Hydraulic Fluid. Confirm Fluids Checked: Fuel Level. N/A: Transmission Fluid

Paint
No visible damage

Body Panels
No visible damage or missing components

Cab/Canopy Overhead Structural Framework
No visible damage

Steps
No visible damage or missing components

Hand Rails
No visible damage or missing components

Exterior Lights
All lights operational

Serial Number / VIN
>DHKCEBDPLR0002159<

SAFETY

Travel Alarm
Operational

Horn
Operational

Seat Belts
Operational

Safety Lock Out/Stop
Operational

Swing Brake
Operational

Current Safety Manual
Yes

Current Operator/Maintenance Manual
Yes

CONTROL STATION

Seat/Armrests
No visible damage or missing components

Glass
No visible damage or missing components

Cab Door
No visible damage or missing components

Steering Controls
Rating:
Good

Hydraulic Controls
Rating:
Good

Drivetrain Controls

Rating:
Good

Dash Console
Rating:
Good

Engine Oil Pressure
The fault indicator shuts off after the engine oil pressure rises.

Warning Lights
Operational

Gauges
Operational

Rear View Camera
Camera operates as intended

Air Conditioner
Operational

Heater
Operational

Limited Function Check (Control Station)
The main components are in place and operational as noted.

 Control Station
Cab Details:, Air Conditioner, Control Pattern Changer


Hour Meter / Odometer
45 hrs

Hour Meter /Odometer Usage Reading (Start)
44.4 hrs

ENGINE

A/C Compressor
Operational

Blow-by (Subjective Visual Observation)
No noticeable vapor or pressure

 Starter
Operational

Exhaust System
No visible damage or missing components

Radiator
Rating:
Good

Oil Leaks
No dripping leaks

Fuel Leaks
No dripping leaks

Cooling System Leaks
No dripping leaks

Limited Function Check (Engine)
The engine started and ran.



Emission Status
Tier 4

Engine
2024 US EPA Label, Requires Diesel Exhaust Fluid

DRIVETRAIN

Left Drive Motor
Rating:
Good

Right Drive Motor
Rating:
Good

Left Final Drive
Rating:
Good

Right Final Drive
Rating:
Good

Limited Function Check (Drivetrain)
The drivetrain was operational.

HYDRAULICS

Pumps (Hydraulics)
Rating:
Good

Valves
Rating:
Good

Hydraulic Tank
Rating:
Good

Hydraulic Control Pattern Changer
Rating:
Good

Hoses (Hydraulics)
Rating:
Good

Auxiliary Hydraulic Plumbing
Capped off, Not operationally checked, End of stick

Swing Motor

Rating:

Good

Hydraulic Center Swivel

Rating:

Good

Boom Lift Cylinder(s)

Rating:

Good

Stick Cylinder

Rating:

Good

Bucket Cylinder

Rating:

Good

Limited Function Check (Hydraulics)

The hydraulic system was operational.

CHASSIS

Boom/Stick Details

Standard Boom, 9 ft 7 in Stick, Auxiliary Hydraulic Plumbing, Stick Check Valve, Boom Check Valves

Boom Condition

Rating:

Good

Stick Condition

Rating:

Good

Boom Base Pin And Bushings

Rating:

Good

Pin And Bushings Boom To Stick

Rating:

Good

Pin And Bushings Stick To Bucket

Rating:

Good

Turntable Bearing

Rating:

Good

Bottom Covers

Rating:

Good

Limited Function Check (Chassis)

The main components were operational in a limited check.

UNDERCARRIAGE

Left Roller Frame
Rating:
Good

Left Track Tensioner
Rating:
Good

Left Track Pads
32 in Wide Triple Grouser
Rating:
Good

Left Grouser Height
24 mm

Left Track Links
101 mm

Left Track Bushings
new mm

Left Carrier Rollers
2 carrier rollers #1 120 mm #2 120 mm

Left Bottom Rollers
8 Bottom Rollers #1 140 mm #2 140 mm #3 140 mm #4 140 mm #5 140 mm #6 140 mm #7 140 mm #8 140 mm

Left Idler
new mm

Left Sprocket
Rating:
Good

Right Roller Frame
Rating:
Good

Right Track Tensioner
Rating:
Good

Right Track Pads
32 in Wide Triple Grouser
Rating:
Good

Right Grouser Height
24 mm

Right Track Links
101 mm

Right Track Bushings
new mm

Right Carrier Rollers
2 Carrier Rollers #1 120 mm #2 120 mm

Right Bottom Rollers
8 Bottom Rollers: #1 140 mm #2 140 mm #3 140 mm #4 140 mm #5 140 mm #6 140 mm #7 140 mm #8 140 mm

Right Idler
new mm

Right Sprocket
Rating:
Good

SPECIALTY

Excavator Bucket Condition
Rating:
Good

Bucket Cutting Edge/Shanks/Teeth
Rating:
Good

Front Attachment
49 in Digging Bucket, Develon

LOGISTICS INFORMATION

Shipping Dimensions
31 ft 9 in Long x 10 ft 6 in Wide x 11 ft Tall 52086.0 lb Shipping Weight

General Shipping Information
Yes: Does this Unit Run? Yes: If self propelled, does the unit travel? Yes: Is the unit wider than 8'6"? Yes: Inflated
Tires - item can roll? No: Is the unit taller than 12'? No: Noticeable fluid leaks?

RECONDITIONING