

## Detailed Equipment Information

[Print](#)

[Download All Photos](#)

2020 DOOSAN DX300LC-5 / HEX



- [Find it in Yard](#)
- [General Appearance](#)
- [Control Station](#)
- [Engine](#)
- [Drivetrain](#)
- [Hydraulics](#)
- [Chassis](#)
- [Undercarriage](#)
- [Specialty](#)

### FIND IT IN YARD

ASSIGNED LANE AND SPOT	Located in Lane 42 Spot 20
------------------------	----------------------------

[Back To Top](#)

### GENERAL APPEARANCE

SERIAL NUMBER / VIN	DHKCEEAAN0021903	
SELLER REFERENCE NUMBER	Seller Reference or Fleet Number:	
TIRES/ UNDERCARRIAGE	Percentage Rating:, 70	
HOUR METER / ODOMETER	520 hrs	
CONDITION	Overall Condition for Age:, Good	
FEATURES	Located in Lane 42 Spot 20, Air Conditioner, Straight Travel Pedal, Rear View Camera, 2022 US EPA Label, 12 ft 6 in Stick, Auxiliary Hydraulic Plumbing, 33.5 in Triple Grouser Track Shoes, Hydraulic Quick Coupler, 46 in Digging Bucket, Auto Lube	

[Back To Top](#)





Photo 1



Photo 2



Photo 3

**CONTROL STATION**

<b>CONTROL STATION</b>	Cab Details:, Air Conditioner, Straight Travel Pedal, Rear View Camera
<b>LIMITED FUNCTION CHECK</b>	The main components are in place and operational as noted.

[Back To Top](#)

- Photo 1
- Photo 2
- Photo 3
- Photo 4
- Photo 5
- Photo 6

**ENGINE**

<b>ENGINE</b>	2022 US EPA Label
<b>LIMITED FUNCTION CHECK</b>	The engine started and ran.

[Back To Top](#)

- Photo 1
- Photo 2
- Photo 3
- Photo 4

**DRIVETRAIN**

<b>LIMITED FUNCTION CHECK</b>	The drivetrain was operational.
-------------------------------	---------------------------------

[Back To Top](#)

**HYDRAULICS**

<b>LIMITED FUNCTION CHECK</b>	The hydraulic system was operational.
-------------------------------	---------------------------------------

[Back To Top](#)

- Photo 1
- Photo 2
- Photo 3
- Photo 4

**CHASSIS**

<b>BOOM/STICK DETAILS</b>	Standard Boom, 12 ft 6 in Stick, Auxiliary Hydraulic Plumbing
<b>LIMITED FUNCTION CHECK</b>	The main components were operational in a limited check.












[Back To Top](#)

- Photo 1
- Photo 2
- Photo 3
- Photo 4
- Photo 5
- Photo 6
- Photo 7

**UNDERCARRIAGE**

<b>UNDERCARRIAGE</b>	33.5 in Triple Grouser Track Shoes
----------------------	------------------------------------








[Back To Top](#)

-  Photo 1
-  Photo 2
-  Photo 3
-  Photo 4
-  Photo 5
-  Photo 6
-  Photo 7
-  Photo 8
-  Photo 9
-  Photo 10
-  Photo 11

**SPECIALTY**

<b>FRONT ATTACHMENT</b>	Hydraulic Quick Coupler, 46 in Digging Bucket
<b>CHASSIS</b>	Auto Lube

[Back To Top](#)

-  Photo 1
-  Photo 2
-  Photo 3
-  Photo 4
-  Photo 5
-  Photo 6
-  Photo 7

**DISCLAIMER**

**General**

The Detailed Equipment Information is limited in scope, and Ritchie Bros. Auctioneers has not inspected any aspects or components of the equipment other than those expressly set forth herein. Unless expressly stated, we make no representations or warranties, express or implied, concerning the equipment or its components, including without limitation any representations or warranties concerning functionality, conformity or compliance with any safety standard or requirement of any applicable authority or regulatory body, fitness for any particular purpose, or merchantability. You are strongly advised to perform your own detailed inspection of the equipment prior to bidding.

**Functions**

Equipment is not tested under load. We make no representation or warranty that equipment is operating in accordance with manufacturers' specifications. No inspection has been performed with respect to any functionality aspect other than those expressly included herein. Only select photos have been provided for individual undercarriage components, and may not be indicative of the condition of the entire undercarriage as a whole.

**Dimensions**

Measurements are given as an estimate only. Actual loaded dimensions may vary based on truck/trailer height and the loaded machine configuration/position. It is the buyer's responsibility to measure all loads before leaving our auction site to ensure the load is safe for transport. All measurements should be verified by the buyer. DO NOT rely on these measurements for transportation purposes