



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #15863791 - 2023 Doosan DX190W-7 Wheel Excavator



Item Details:

- Features: Air Conditioner, Air Ride Seat, Control Pattern Changer, Rear & Side View Cameras, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 8 ft 6 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, 10.00x20 Tires
- Meter Reading: 2,323 Hours
- Serial # : DHKCEWCKHN5001060
- Inspection Completed: 9/9/26

Shipping Details:

- Location New Brunswick
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance



Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	DHKCEWCKHN5001060	
Hour Meter / Odometer	2323 hrs	
v3 General Appearance # 1		
v3 General Appearance # 2		
v3 General Appearance # 3		
v3 General Appearance # 4		
Paint		


Sheet Metal (fiberglass) Condition		
Steps/Ladders		
Hand Rails		
Glass		
Exterior Lights	Operational	

Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Safety Lock Out/Stop	Operational	
Swing Brake	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	Yes	
Excavator_2 # 1		

Control Station		
Item	Assessment	Photo
Control Station #1		
Control Station #2		
Control Station #3		
Control Station #4		
Control Station #5		
Control Station #6		

Mirrors		
Seats/Armrests		
Steering Control	★★★★☆	
Hydraulic Controls	★★★★☆	
Drivetrain Controls	★★★★☆	
Oil Pressure	No oil pressure indicator	
Warning Lights	Operational	
Gauges	Operational	

Air Conditioner	Operational	
Heater	Operational	
Limited Function Check	The main components are in place and operational as noted.	

Engine		
Item	Assessment	Photo
Engine	2022 US EPA Label, Requires Diesel Exhaust Fluid	
v2 Engine # 1		
v2 Engine # 2		
v2 Engine # 3		
v2 Engine # 4		
v2 Engine # 5		
v2 Engine # 6		

Emission Label		
A/C Compressor	Operational	
Starter	Operational	
Exhaust System		
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	
Engine - Left Side		
Engine - Right Side		

DEF / AdBlue Tank		
Limited Function Check	The engine started and ran.	


Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.


Item	Assessment	Photo
Drive Motors	★★★★☆	
Front Drive Axle	★★★★☆	
Front Axle Oscillating Pin	★★★★☆	
Rear Drive Axle	★★★★☆	
Drive Line	★★★★☆	
Final Drives	★★★★☆	
Limited Function Check	The drivetrain was operational.	

Drivetrain #1		
Drivetrain #2		
Drivetrain #3		
Drivetrain #4		
Drivetrain #5		
Drivetrain #6		
Drivetrain #7		

Drivetrain #8		
---------------	--	---

Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hydraulic Control Pattern Changer	★★★★☆	
Hoses (Hydraulics)	★★★★☆	
Auxiliary Hydraulic Plumbing	Operational, Capped off, End of stick, Plus plumbing for Q/A	

Swing Motor	★★★★☆	
Hydraulic Center Swivel	★★★★☆	
Boom Lift Cylinder(s)	★★★★☆	
Stick Cylinder	★★★★☆	
Bucket Cylinder	★★★★☆	
Blade Lift Cylinder	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Excavator_2 # 1		

Excavator_2 # 2		
Excavator_2 # 3		
Excavator_2 # 4		
Excavator_2 # 5		
Excavator_2 # 6		
Excavator_2 # 7		
Excavator_2 # 8		

Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Chassis #1		
Chassis #2		
Boom Condition	★★★★☆	
Stick Condition	★★★★☆	
Boom Base Pin and Bushings	★★★★☆	
Pin and Bushings Boom to Stick	★★★★☆	

Pin and Bushings Stick to Bucket	New Pins Installed	
Turntable Bearing	★★★★☆	
Bottom Covers		
Roller Frames	★★★★☆	
Stabilizers	★★★★☆ Operational	
Limited Function Check	The main components were operational in a limited check.	
Steering Linkage	★★★★☆	

Frame Condition	★★★★☆	
Limited Function Check	The main chassis components functioned during a limited check.	
Brake Control	★★★★☆	
Park Brake	★★★★☆ Stopped from a slow roll	
Limited Function Check - Brakes	The brake system functioned, stopping and holding the machine.	
Left Front Tire		
Left Rear Tire		
Right Rear Tire		
Right Front Tire		
Wheel Condition	★★★★☆	
Wheel Studs, Nuts, Lugs	★★★★☆	

Specialty		
Item	Assessment	Photo
Specialty #1		
Blade Condition	☆☆☆☆	
Blade Cutting Edge Condition	☆☆☆☆	

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved